

Report ID: 22,988,123 1 Version: 05 Jan 2025 Created:

Make:       Holden       Model:       Commodore       Body Style:       Utility         Ver       2018       Registration:	ail N/A		
Wolf Expiry:       03 Jan 2026       Odometer:       209.523 Kms       Good No:       22980123         VIN:       601FPA4E34H122005       Next Service:       225.000 Kms       Service History       No         Mote:       Different is a quide only. Consideration is made for age and mileage. Parts have not been dismanted or all different is not been arged for an additional charge.       Noise       ////         Key:       SDPTSC       DSC       Soft       Performance       //         S = scratch       D = dent.       SDPTSC       DSC       Soft       Performance       //         P = pin dent:       SD D C       SS SC       SS SC       Coloint Condition       //       Performance       //         S = conce hips       SD SC       SS SC       SS SC       Coloint Condition       //       Performance       //       Coloint Condition       //       Performance       //       Coloint Condition       Coloint Condition       //       Coloint Condition       // <t< td=""><td></td></t<>			
Vite:       6GIT/A4E3XHL329005       Next Service:       225,000 Kms       Service History:       No         Note:       This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or a full mechanical inspection prior to purchase and this can be arranged for an additional charge.       Smoke & furmes       V         Key:       SDTSC       DSC       SDSC       SDSC       Radiator / Holes (Visual)       Radiator / Holes (Visual)         D = dent       SDTSC       SDSC       SDSC       Radiator / Holes (Visual)       Radiator / Ho			
Note: This report is a guide only. Consideration is made for age and mileage. Parts have not been dimanted or afulamented instrume up to \$50m? From cold. The vendor recommends of afulamenter instrume which has been driven up to \$50m? From cold. The vendor recommends of the vendor recomponed of the vendor recommend			
Note:       V         Inits report is a quide only. Consideration is made for age and mileage. Parts have not been dismanted or a quide only. Consideration is can be arranged for an additional charge.       Inote:       V         Init and mechanical inspection prior burchase and this can be arranged for an additional charge.       Condiant condition       V         Key:       SD PT SC       D SC       SD SC       Rediator / Hoses (visual)       V         S = scratch       D = dent       S PT SC       SD SC       Rediator / Hoses (visual)       V         P = pin defect       C = cock       S D SC       SD SC       Noise       V       Rediator / Hoses (visual)       V         S = scratch       S D SC       SD SC       SD SC       SD SC       Noise       V       Rediator / Hoses (visual)       V       Rediator / Hoses			
Interference       Image: Construction of the large and interage: Parts have individe up to the large individe up to the large individes of the	 		
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.       Image J Alman         Key:       S D T SC       D SC       V         S = scratch       S D T SC       V       Performance       V         R = nust       S T SC       S C       V       Performance       V         P = pin dent       S D SC       S D SC       V       Noise       V       Clouds         S = atone chips       S D SC       S D SC       S D SC       V       Noise       V       Clouds       V       Noise       V       Noise       V       Noise       V       D       Readditor / Hoses (Visual)       V       Noise       V       D       Readitor / Hoses (Visual)       Note: Sond (Visual)       V       D       Readitor / Hoses (Visual)       Note: Sond (Visual)       Note: Sond (V			
Key:       S D FT SC       D SC       S D SC         S = stratch       D = dent       S T SC       Radiator / Hoses (visual)       V         R = nsit       S D SC       S D SC       D = dent       S D SC         P = pin defect       C = crack       S D SC       S D SC       C = decais         S D SC       S D SC       S D SC       S D SC       C = decais         S C = stone chips       S D SC       S D SC       S D SC       C = decais         S C = stone chips       Note: some defects & blemishes may not be displayed in the diagram       Holes dilled in canopy orot, hare canopy window scuffed.       2 additional aerial points on roof.       D rivers door seal torn.         Holes dilled in front bummer fits noorly on 1H side.       Drivers door seal torn.       T res       Spare       Yes         Under Carriage & Under Bonnet Inspection Comments       Drivers door seal torn.       Spare       Yes       Spare       V         Interior Comments       Seats       Good       I       I       I       I         Seats       Good       I       I       I       I       I         Interior Comments       Seats       Good       I       I       I       I         Seats       Good       I	1		
Key:       SDFISC       DSC       SDSC         S scratch			
S = stratch D = dent F = nst T = pin defect C = crack P = pin dent * = decals S D SC S = stone chips W = significant scuffs S D SC S = stone chips W = significant scuffs S D SC S = stone chips W = significant scuffs S D SC S D S			
D = dent       SPT SC.         P = paint defect       C = crack         P = pin dent       SD SC         * = decals       SD SC         SC = stone chips       SD SC         Body Inspection Comments       Note: some defects & blemishes may not be displayed in the diagram         Holes drilled in front bumper blanks.       RH dog cage window damaged.         Holes drilled in front bumper blanks.       RH dog cage window damaged.         Holes drilled in front bumper blanks.       RH dog cage window damaged.         Holes drilled in front bumper blanks.       RH dog cage window scuffed.         2 additional serial ports on roof.       Drivers door seal torn.         Front bumper fits noort/v on 1H side.       Tryres (lowest observed tread depth of the lagram         Under Carriage & Under Bonnet Inspection Comments       Suspension         Suspension performance       ✓         Steering performance       ✓         Stock absorbers       ✓         Stock absorbers       ✓         Dashboard       Poor, holes drilled in centre console.         Dashboard       Poor, holes drilled			
R = rust       •         P = paint defect       •         C = crack       P = pint deft         S = stone fulps       •         W = significant scuffs       S D SC         S = stone fulps       •         Body Inspection Comments       Note: some defects & blemishes may not be displayed in the diagram         Holes drilled in front bumper blanks.       RH dog cage window damaged.         Holes drilled in anopy roof, taped over.       Rear canopy window scuffed.         2 additional serial ports on roof.       Drivers door seal torn.         Front bumper fits oaorly on LH side.       Itel front         Under Carriage & Under Bonnet Inspection Comments       Suspension         Suspension       Suspension performance         Suspension performance       •         Stock absorbers       •         Interior Comments       •         Seats       Good         Carpets       Average, holes drilled in centre console.         Panels       Poor, holes drilled and dash speaker trim missing.         Mindow winder FR       •         Window winder RR       •         Mindow winder RR       •         Mindow winder RR       •	<b>v</b>		
Interior Comments       Sc       Clutch       Image: Clutch         Sc = stone chips       SD SC       SD SC       Wheel bearings       V         Body Inspection Comments       Note: some defects & blemishes may not be displayed in the diagram       Performance       V         Holes drilled in front bumper blanks.       RH dog cage window damaged.       Hand Brake       V         Holes drilled in canopy root, taped over.       Rear canopy window scuffed.       Pres (lowest observed tread depth of tage and the canopy root aped ver.         Yores (lowest observed tread depth of tage and the canopy window scuffed.       Drivers door seal torn.       Pres (lowest observed tread depth of tage and the canopy window scuffed.         2 additional aerial ports on roof.       Drivers door seal torn.       Pres (lowest observed tread depth of tage and tage)         Vinder Carriage & Under Bonnet Inspection Comments       Suspension       Suspension         Suspension       Suspension performance       V         Static Conditioning / Heater       Operation       V         Operation       V       Indicators       V         Panels       Poor, holes drilled in passenger footwell.       Indicators       V         Panels       Poor, holes drilled and dash speaker trim missing.       Dashboard       Poor, holes drilled and dash speaker trim missing.         Sundow wi			
P = pin dent       S D SC       C V joints       V         S = stone chips       S D SC       S D SC       Wele bearings       V         Body Inspection Comments       Note: some defects & blemishes may not be displayed in the diagram       Brakes       V         Holes drilled in front bumper blanks.       RH dog cage window damaged.       Hand Brake       V         Holes drilled in front bumper blanks.       RH dog cage window damaged.       Left front       4         Yerse (lowest observed tread depth of the case deph of the case depth of the case deph of the case deph of the case	~		
* = decals SD SC SC = stone chips SC = stone chips W = significant scuffs SD SC Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram Holes drilled in font bumper blanks. RH dog cage window damaged. Holes drilled in font bumper blanks. RH dog cage window damaged. Holes drilled in font bumper blanks. RH dog cage window damaged. Holes drilled in font bumper blanks. RH dog cage window damaged. Holes drilled in canopy roof, taped over. Rear canopy window scuffed. 2 additional aerial ports on roof. Drivers door seal torn. Front bumper fits boortv on LH side. Under Carriage & Under Bonnet Inspection Comments Under Carriage & Under Bonnet Inspection Comments Seats Good Carpets Average, holes drilled in passenger footwell. Dashboard Poor, holes drilled in centre console. Dashboard Poor, holes drilled and dash speaker trim missing. General Comments Canopy keys provided only work for LH side window. No keys for other canopy locks - RH side window.	<b>-</b>		
SC = stone chips       Writeen Costings       V         Body Inspection Comments       Note: some defects & blemishes may not be displayed in the diagram         Holes drilled in front bumper blanks.       RH dog cage window damaged.         Holes drilled in canopy roof, taped over.       Rear canopy window scuffed.         2 additional aerial ports on roof.       Drivers door seal torn.         Front bumper fits noorly on LH side       Prior         Under Carriage & Under Bonnet Inspection Comments       Spare         Vinder Carriage & Under Bonnet Inspection Comments       Suspension performance         Steering performance       V         Shock absorbers       V         Air Conditioning / Heater       Operation         Operation       V         Indicators       V         Head lights       V         Tail lights       V			
W = significant scutts       S D SC       S D SC       Performance       V         Body Inspection Comments       Note: some defects & blemishes may not be displayed in the diagram       Hand Brake       V         Holes drilled in front bumper blanks.       RH dog cage window damaged.       Hand Brake       V         Holes drilled in canopy roof, taped over.       Rear canopy window scuffed.       Divers door seal torn.       Effet front       4         Front bumper fits noorly on LH side.       Drivers door seal torn.       Front bumper fits noorly on LH side.       T         Under Carriage & Under Bonnet Inspection Comments       Suspension performance       V       Suspension performance       V         Interior Comments       Seats       Good       Interior Average, holes drilled in passenger footwell.       Head lights       V       Indicators       V         Panels       Poor, holes drilled in centre console.       Dashboard       Poor, holes drilled in dash speaker trim missing.       Window winder FR       V         Window winder FR       V       Window winder RR       V			
Body Inspection Comments       Note: some defects & blemishes may not be displayed in the diagram         Holes drilled in front bumper blanks.       RH dog cage window damaged.         Holes drilled in canopy roof, taped over.       Rear canopy window scuffed.         2 additional aerial ports on roof.       Drivers door seal torn.         Front bumper fits noorly on LH side.       Itel thront         Conditions During Body Inspection:       Dry         Under Carriage & Under Bonnet Inspection Comments       Spare         Vertice Interior Comments       Vertice         Seats       Good       Vertice         Carpets       Average, holes drilled in centre console.       Vertice         Dashboard       Poor, holes drilled and dash speaker trim missing.       Vertice         General Comments       General Comments       Vertice         General Comments       Vertice       Vindow winder FR         Ganopy keys provided only work for LH side window. No keys for other canopy locks - RH side window       Window winder RR			
Body Inspection Comments       Tyres (lowest observed tread depth of the depth of	_		
Holes drilled in front bumper blanks.       RH dog cage window damaged.       Left front       4         Holes drilled in canopy roof, taped over.       Rear canopy window scuffed.       Right front       4         2 additional aerial ports on roof.       Drivers door seal torn.       Right front       4         Front bumper fits poorly on LH side.       Drivers door seal torn.       Right front       4         Conditions During Body Inspection:       Dry       Right rear       4.5         Spare       Yee       Suspension       Suspension       Suspension         Interior Comments       Suspension performance       ✓       Steering performance       ✓         Seats       Good        Had lights       ✓       Indicators       ✓         Panels       Poor, holes drilled in centre console.       Dashboard       Point Support (fort & rear)       ✓       Indicators       ✓			
Holes drilled in canopy roof, taped over.     Rear canopy window scuffed.     Iter tront     4       2 additional aerial ports on roof.     Drivers door seal torn.     Right front     4       Right front     4       Right front     4       Left rear     7       Conditions During Body Inspection:     Dry     Right rear     4.5       Under Carriage & Under Bonnet Inspection Comments     Suspension performance     ✓       Suspension performance     ✓     1       Steering performance     ✓     1       Shock absorbers     ✓     1       Steering performance     ✓     1       Good     Carpets     Average, holes drilled in passenger footwell.     Head lights     ✓       Dashboard     Poor, holes drilled and dash speaker trim missing.     Window winder FL     ✓       Window winder FR     ✓     1       Window winder RR     ✓     1			
Front bumper fits noorly on LH side.       Left rear       7         Conditions During Body Inspection:       Dry       Right rear       4.5         Under Carriage & Under Bonnet Inspection Comments       Suspension performance       ✓         Suspension performance       ✓       Stering performance       ✓         Interior Comments       ✓       Stering performance       ✓         Seats       Good       Air Conditioning / Heater       Operation       ✓         Carpets       Average, holes drilled in passenger footwell.       Indicators       ✓       Indicators       ✓         Dashboard       Poor, holes drilled and dash speaker trim missing.       Operation dash speaker trim missing.       Window winder FR       ✓         General Comments       Canopy keys provided only work for LH side window. No keys for other canopy locks - RH side window       Window winder RR       I	mm		
Conditions During Body Inspection:       Dry         Under Carriage & Under Bonnet Inspection Comments       Right rear       4.5         Spare       Ye         Suspension       Suspension performance       V         Steering performance       V       Shock absorbers       V         Shock absorbers       V       Atr Conditioning / Heater         Operation       V       Electrical / Accessories         Karpets       Average, holes drilled in passenger footwell.       Head lights       V         Dashboard       Poor, holes drilled and dash speaker trim missing.       Dashboard warning lights       V         General Comments       Window winder FR       V       Window winder RR       Window winder RR	mm		
Under Carriage & Under Bonnet Inspection Comments       Spare       Yes         Spare       Yes         Spare       Yes         Suspension       Suspension performance       ✓         Steering performance       ✓       Steering performance       ✓         Shock absorbers       ✓       Steering performance       ✓       Steering performance       ✓         Interior Comments       Sood       Air Conditioning / Heater       Operation       ✓       Steering Performance	mm		
Under Carriage & Under Bonnet Inspection Comments       Suspension         Suspension performance       ✓         Suspension performance       ✓         Steering performance       ✓         Shock absorbers       ✓         Air Conditioning / Heater       Operation         Operation       ✓         Seats       Good         Carpets       Average, holes drilled in passenger footwell.         Panels       Poor, holes drilled in centre console.         Dashboard       Poor, holes drilled and dash speaker trim missing.         General Comments       ✓         Ganopy keys provided only work for LH side window. No keys for other canopy locks - RH side window       Window winder RR	mm		
Interior Comments       Suspension performance       ✓	<u>'S</u>		
Seering performance       ✓         Shock absorbers       ✓         Shock absorbers       ✓         Air Conditioning / Heater       Operation       ✓         Operation       ✓       I         Seats       Good       ✓       I         Carpets       Average, holes drilled in passenger footwell.       Head lights       ✓       I         Panels       Poor, holes drilled in centre console.       Dashboard warning lights       ✓       I         Dashboard       Poor, holes drilled and dash speaker trim missing.       Window winder FL       ✓       I         General Comments       Window winder FR       ✓       I       I         Canopy keys provided only work for LH side window. No keys for other canopy locks - RH side window       Window winder RR       I			
Interior Comments       Shock absorbers       ✓         Seats       Good       ✓         Carpets       Average, holes drilled in passenger footwell.       Head lights       ✓         Panels       Poor, holes drilled in centre console.       Dashboard       Poor, holes drilled and dash speaker trim missing.         General Comments       Window winder FL       ✓         General Comments       Window winder RR       ✓			
Interior Comments       Air Conditioning / Heater         Seats       Good         Carpets       Average, holes drilled in passenger footwell.         Panels       Poor, holes drilled in centre console.         Dashboard       Poor, holes drilled and dash speaker trim missing.         General Comments       V         Canopy keys provided only work for LH side window. No keys for other canopy locks - RH side window       Window winder RR			
Interior Comments       Operation       Image: Comments         Seats       Good       Electrical / Accessories         Carpets       Average, holes drilled in passenger footwell.       Head lights       Image: Comments         Panels       Poor, holes drilled in centre console.       Indicators       Image: Comments         Dashboard       Poor, holes drilled and dash speaker trim missing.       Window winder FL       Image: Comments         General Comments       Canopy keys provided only work for LH side window. No keys for other canopy locks - RH side window       Window winder RR       Image: Comment RR			
Interior Comments         Seats       Good         Carpets       Average, holes drilled in passenger footwell.       Head lights       ✓         Panels       Poor, holes drilled in centre console.       Indicators       ✓         Dashboard       Poor, holes drilled and dash speaker trim missing.       ✓       Dashboard warning lights       ✓         General Comments       Window winder FR       ✓       ✓       ✓         Canopy keys provided only work for LH side window. No keys for other canopy locks - RH side window       Window winder RR       ✓			
Seats       Good       Head lights       ✓         Carpets       Average, holes drilled in passenger footwell.       Indicators       ✓         Panels       Poor, holes drilled in centre console.       Dashboard       Dashboard warning lights       ✓         Dashboard       Poor, holes drilled and dash speaker trim missing.       ✓       Window winder FL       ✓         General Comments       Canopy keys provided only work for LH side window. No keys for other canopy locks - RH side window       Window winder RR       ✓			
Carpets       Average, holes drilled in passenger footwell.         Panels       Poor, holes drilled in centre console.         Dashboard       Poor, holes drilled and dash speaker trim missing.         General Comments       V         Canopy keys provided only work for LH side window. No keys for other canopy locks - RH side window       Window winder RR			
Carpets       Average, holes drilled in passenger footwell.       Indicators       Indicat			
Panels       Poor, holes drilled in centre console.         Dashboard       Poor, holes drilled and dash speaker trim missing.         General Comments       Window winder FR         Canopy keys provided only work for LH side window. No keys for other canopy locks - RH side window       Window winder RR			
Dashboard       Poor, holes drilled and dash speaker trim missing.         Wipers (front & rear)       ✓         Window winder FL       ✓         General Comments       Window winder FR       ✓         Canopy keys provided only work for LH side window. No keys for other canopy locks - RH side window       Window winder RR       ✓			
Dashboard       Poor, holes drilled and dash speaker trim missing.       Window winder FL       V         General Comments       Window winder RR       V         Canopy keys provided only work for LH side window. No keys for other canopy locks - RH side window       Window winder RR       I			
General Comments     Window winder FL     ✓       Canopy keys provided only work for LH side window. No keys for other canopy locks - RH side window     Window winder RL     ✓			
General Comments     Window winder RL       Canopy keys provided only work for LH side window. No keys for other canopy locks - RH side window     Window winder RR			
Canopy keys provided only work for LH side window. No keys for other canopy locks - RH side window Window winder RR			
currently keys provided only work for Errstade window, no keys for other europy toeks in this de window	~		
	~		
locked. Steering wheel audio controls not working.			
Canopy high stop light fail. One key remote not working. Radio (basic test only)			
CD (basic test only)	~		
Number of keys 3			
Road Conditions During Test Drive: Dry Central locking 🖌			
Remote locking 🖌			
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)	~		
Evidence of Cam Belt Replacement: Not Applicable Kms: Reversing camera 🖌			
Inspected by: Troy Smith Date: 05 Jan 2025			

I have read and understood this condition guide.

Name: .....

Signature: .....