

Report ID: 22,988,414 Version: 1 24 Dec 2024 Created:

Make:	Toyota	Model:	Hilux	Body Style:	Utility		Pass	Fail	N/A
Year:	2005	Registration:	DAH543	Reg Expiry:	08 Aug 2025	Engine	1	<u> </u>	
WoF Expiry:		Odometer:	459,173 Kms	Good No:	22988414	Oil level	~		<u> </u>
VIN:	MR0CZ12G40000377;	Next Service:	461,797kms	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
	D SC SC		S D * SC	SC		Performance	~		
Key:	D'sc []sc	-0				Radiator / Hoses (visual)	~		-
S = scratch	TE	Transmission			1				
D = dent R = rust				715	HIV	Operation	~		
PT = paint defe		IT I		$\left( \left  \left( \right) \right\rangle \right)$	7014	Noise	~		
C = crack					S R P SC	Clutch	~		
P = pin dent	PSC DE				74116	CV joints			~
* = decais						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant scutts P SC SC SP * SC SC SC SC						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
body inspection comments						Tyres (lowest observed trea	<b>Tyres</b> (lowest observed tread depth of tyres)		
Front bumper damaged & spot light blanks missing.						Left front 8 r			mm
Rust spot on roof above windscreen. Grille broken.						Right front	9	9	mm
						Left rear		7	mm
Conditions During Body Inspection: Dry						Right rear	1	7	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			1
Seats	Seats Large hole in drivers seat, all stained.					Head lights	~		
						Tail lights	~		
Carpets	Hole on di	rivers side.				Indicators	~		
Panels	Average, v	vorn.			1	Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	ra Cup holde	er faces missing, s	teering wheel worn.			Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL			~
T-belt light on.						Window winder RR			~
2WD diesel manual single cab flat deck.						Rear view mirrors			~
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
	-					Remote locking			~
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Yes Kms: 305,000						Reversing camera			~
la a	d by: Daryll Timms					Date: 24 Dec 20	124		
Inspected						Date: 24 Dec 20	27		

I have read and understood this condition guide.

Name: .....

Signature: .....