

Report ID: 25,090,782 5 Version: 12 Dec 2024 Created:

Make:	Mitsubishi	Model:	Triton	Body Style:	Utility		Pass	Fail	N/A
Year:	2017	Registration:	KUR147	Reg Expiry:	20 Mar 2025	Engine			
WoF Expiry:	13 Nov 2025	Odometer:	179,267 Kms	Good No:	25090782	Oil level	~		
VIN:	MMAJYKK10HH019943	Next Service:	183,000kms	Service History	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional c	harge.	Coolant condition	~		
	S SC		P SC SC	S	P SC	Performance	~		
Key:		=		500		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust SC A A SC						Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack					S SC	Clutch			~
P = pin dent	PSC DE				74Hb	CV joints			~
* = decais						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
P SC P SC D SC						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
					Tyres (lowest observed tread depth of tyres)				
Surface rust & scratches on roof at top of windscreen. Holes in roof mouldings.					Left front	6.0 mm			
Dents on left cab corner.						Right front	6.0 mm		mm
Riaht runnina board bent.					Left rear	7.	.0	mm	
Conditions During Body Inspection: Dry					Right rear	7.0 mm		mm	
						Spare	re Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Suspension perf						Suspension performance	~		
Steering p							~		
	Shock absorbers	~							
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Hole in dri	ivers seat, rear se	at stained.			Head lights	~		
Carpets	A					Tail lights	~		
Carpets	Average					Indicators	~		
Panels R/H A pillar grab handle needs refitting.					Dashboard warning lights	~			
Dashboa	rd Chantana					Wipers (front & rear)	~		
Dastibua	Steering w	/neel worn, centr	e vent damaged.			Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>					Window winder RL	~			
2WD diesel auto d/cab ute.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanism: Timing Chain						Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	oi Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Daryll Timms Date: 06 Dec 2024									

I have read and understood this condition guide.

Name:

Signature: