

Basic Vehicle Condition Guide

Report ID: 26,236,362


Version: 2

Created: 21 Sep 2024

Make: Model: Mitsubishi Triton **Body Style:** Utility Year: 2006 Registration: **DNA595** Reg Expiry: 05 Jan 2025 WoF Expiry: **Odometer:** 16 Mar 2025 316,292 Kms **Good No:** 26236362 VIN: MMBJNKB907D03490 Next Service: 316,531 Kms Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chip in front windscreen Front park lights aren't working Left side plastic bumper trim is missing Crack and moisture in right rear tail light Rust on exterior door pillars and above on roof

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Rust on underside of bonnet Transmission oil weep and seepage Coolant reservoir has temporary lid

| Interior Commen | <u>ts</u> |
|-----------------|--------------------|
| Seats | Seat covers fitted |
| Carpets | Average |
| Panels | Good |
| Dashboard | Good |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:** Yes

Kms: 300,000

Date: 15 Aug 2024 Inspected by: Hoani Saunders

| | | • | |
|--|--------------|------|-------|
| | Pass | Fail | N/A |
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | | ~ | |
| Performance | V | | |
| Noise | ~ | | |
| Cooling System | | | ı |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | <i>V</i> | | |
| CV joints | \(\times \) | | |
| Wheel bearings | <u>,</u> | | |
| Brakes | | | |
| Performance | | | |
| Hand Brake | | | |
| | 1 dont | of + |) |
| Tyres (lowest observed tread Left front | | | |
| | 6.8 | | mm |
| Right front | 7.0 | | mm |
| Left rear | 2.4 | | mm |
| Right rear | 2 | .0 | mm |
| Spare | | Yes | |
| Suspension | 1 | | |
| Suspension performance | ~ | | |
| Steering performance | <i>V</i> | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | | ~ | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | \(\times \) | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | <u> </u> | ~ | |
| Window winder RR | V | | |
| Rear view mirrors | 1 | | |
| Radio (basic test only) | ., | | |
| | | | |
| CD (basic test only) | 1 | | · · |
| Number of keys | 1 | | |
| Cambriella II | V | | |
| Central locking | | | 1 |
| Remote locking | ~ | | |
| | ' | | ~ |

I have read and understood this condition guide.

Name:

Signature: