

I have read and understood this condition guide.

Report ID: 26,450,018 Version: 1 28 Nov 2024 Created:

Signature:

Name: 2006 Registration: P(N317) Reg Expire: 80 to 2024 Welf Expire: 0.40 median	Make:	BMW	Model:	3251	Body Style:	Wagon		Pass	Fail	N/A
Work Explay: 0.3 dometer: 176,002 kms Good No: 26450018 Vite: Wite Addition State Additions Service History: No: Mott This sputide only (conservation is made for age and milesge Parts have not hem discanded on generative the mage of the additional charges. No: No: No: Service History: No: Service History: No: No: No: No: Service History: Service History: No: No: <t< td=""><td></td><td></td><td></td><td></td><td></td><td>-</td><td>Engine</td><td></td><td></td><td></td></t<>						-	Engine			
VINE Weak Statussion (See A furmes 1) Service History: No Since & furmes 1 Since & fu			2					~		
Note: This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled of dispositions in additional charge. Performance: V Noise: V Noise: V Noise: V Additionation is made for age and mileage. Parts have not been dismantled of dispositions in additional charge. V Noise: Nois: Nois: Nois: Nois: Noi		•								
Note: This report is quide risk only Consideration is made for age and mileage. Pairs have not been dismainted of the distance of the main of the whends is the distance of the main of the whends is the distance of t								-		
Interface of the optimizer is and introduce in the optimizer is an additional darge. Coding System Key: Social processing of the optimizer is and this can be arranged for an additional darge. Coding System Key: Social processing of the optimizer is a difficult darge. Coding System Key: Social processing of the optimizer is a difficult darge. Coding System Social processing of the optimizer is a difficult darge. Coding System Coding System Social processing of the optimizer is a difficult darge. Coding System Coding System Social processing of the optimizer is a difficult darge. Coding System Coding System Social processing of the optimizer is a difficult darge. Coding System Coding System Social processing of the optimizer is a difficult darge. Coding System Coding System Note some datests & blemishes may not be displayed in the diagram. Note some datests & blemishes may not be displayed in the diagram. Note some datests & blemishes may not be displayed in the diagram. Coding										
a full mechanical linguection prior to purchase and this can be arranged for an additional charge. Coolari condition // Key: S S P P S = cleart S S P R = tuit S S P P P = pain diret: S S S P S = store thips S S S V P V = additation / formation V P <t< td=""><td colspan="7">This report is a guide only. Consideration is made for age and mileage. Parts have not been dismanued or</td><td>v</td><td></td><td></td></t<>	This report is a guide only. Consideration is made for age and mileage. Parts have not been dismanued or							v		
Key: S F F S F S F S F S F S F S F S F S F S F S										
Key: S S Pisce (Muul) - S = soratch P = anit diffect - - C = cock (P = pin dent) S S S S = store this S S S - Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram Weel bearings - - No spare wheel, repair kit to jack & tools supplied. Drivers door set id anaged. - - - Conditions During Body Inspection: Dry Ileft rear 6 nm Might rear 6 nm - - - Under Carriage & Under Bonnet Inspection Comments Supersion performance - - - Seats Verage - - - - - Interior Comments Seats Verage -										
S - scatch P - gin dert S - sc	Key:	S S	-0	PT SC SC		Р				
D - dient SC SC Per and defect V C - crack Per and defect V V C - crack SC SC SC V V Se atom exhips SC SC SC V V Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram Note: some defects & blemishes may not be displayed in the diagram Performance V V Driver dour soid damaged. Note: some defects & blemishes may not be displayed in the diagram Note: some defects & blemishes may not be displayed in the diagram Note: some defects & blemishes may not be displayed in the diagram Driver dour soid damaged. Note: some defects & blemishes may not be displayed in the diagram Note: some defects & blemishes may not be displayed in the diagram Under Carriage & Under Bonnet Inspection: Dry Space N/A Supersion Space N/A Space N/A Supersion Space N/A Space N/A Supersion performance V I Space I Steering performance V I I I Deshboard Average V I I	S=scratch									
Interior Comments Seats Ware from to stats. Carpets Average Panels Average Densits V Seats Varage Interior Comments Average Panels Average Panels Average Destators and statistics V General Comments Average Panels Average Panels Average Panels Average Panels Average Proof Average Vindow winder FR Window winder FR V Window winder FR V Read Conditions During Test Drive: Dry Read Conduritions Dur	D = dent									
Interface Control Image: Control Sec = cack Sec = stone chips Sec = stone chips Sec = stone chips Sec = stone chips Sec = stone chips Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram No spare where trapit it or jack & tools supplied. Performance Image: Conditions During Body Inspection: Driver shore seal damaged. Prime shore seal damaged. Image: Conditions During Body Inspection: Dry Under Carriage & Under Bonnet Inspection Comments Bight frant 3 mm Engine oil leaks. Seats Wear on front seats. Image: Conditions/Heater Suspension Interior Comments Seats Wear on front seats. Image: Conditions/Heater Deration V Image: Conditions/Heater Dashboard Average V Image: Conditions/Heater Image: Conditions/Heater Image: Conditions/Heater Perior auto 2321 Touring wagen. Thump in transmission when decelerating, suggest possibly mounts. Image: Conditions During Test Drive: Dry Image: Conditions During Test Drive: Dry Rear locking V Image: Conditions During Test Drive: Dry Image: Conditions Conding: V					10				V	
P = pin dent Image: Construct of the series of the ser	· ·	ect			+			~		
Y = decals SC SC Y Y SC = stoue chips SC SC SC SC Performance Y I Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram No spare wheel, repair kit or jack & tools supplied. Tyres flowest observed tread depth of tyres) Drivers door scal damaged. Front bumper damaged. Tyres flowest observed tread depth of tyres) Under Carriage & Under Bonnet Inspection Comments Dry Right rear 6 mm Munder Carriage & Under Bonnet Inspection Comments Suspension Suspension Suspension I Interior Comments Seats Wear on front seats. Suspension V I I Seats Wear on front seats. Seats Verrage I I I I Panels Average Average V I I I I I I Petroi auto 2251 Touring Wagon. Thump in transmission when decelerating, suggest possibly mounts. I I I I I I I I I I I I I I <td< td=""><td></td><td>Ho</td><td>KI</td><td></td><td></td><td>JIII —</td><td></td><td></td><td></td><td></td></td<>		Ho	KI			JIII —				
SC = stone chips Parket Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram No spare where repair kt or ick & tools supplied. Tyres (lowest observed tread depth of tyres) Drivers door seal damaged. I Conditions During Body Inspection: Dry Under Carriage & Under Bonnet Inspection Comments Bight rear Engine oil leaks. V Interior Comments V Seats Wear on front seats. Carpets Average Panels Average Dashboard Average Sental Conditions During Test Drive: Dry Road Conditions During Test Drive: Dry Central Locking V Road Conditions During Test Drive: Dry Central Locking V Road Conditions During Test Drive: Dry Central Locking V <	I '	sc pp					-			~
W = significant scutts SC SC Performance V Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram No spare wheel, repair kit or jack & tools supplied. Tyres ilowest observed tread depth of tyres) Divers door soal damaged. a Conditions During Body Inspection: Dry Under Carriage & Under Bonnet Inspection Comments Spare Engine oil leaks. Spare Interior Comments V Seats Wear on front seats. Carpets Average Panels Average Panels Average Panels Average Performances V Window winder FR V Window winder FR V Spare view mirrors V Radic Obasit et only) V Vindow winder FR V Radic Obasit et only) V Radic Obasit et only) V Dashboard Verage Pertoal to Szi Touring wagon. Thump in transmission when decelerating, suggest possibly mounts. Road Conditions During Test Drive: Dry								5		
Body Inspection Comments No spare wheel, repair kit or jack & tools supplied. Drivers door seal damaged. Front bumper damaged. Value Value Value Front bumper damaged. Front bumper damaged. Types (lowest observed tread depth of tyres) Left front 3 mm Conditions During Body Inspection: Dry Ileft front 3 mm Under Carriage & Under Bonnet Inspection Comments Spare N/A Suppension performance V 1 1 Engine oil leaks. Spare V 1 2 1 <	W = significant scuffs									
body inspection comments Tyres (lowest observed tread depth of tyres) No spare where the total supplied. Tyres (lowest observed tread depth of tyres) Drivers door seal damaged. I eff front 3 mm Right front 3 mm Right front 6 mm No pare where damaged. Right front 6 mm Under Carriage & Under Bonnet Inspection Comments Supension performance ✓ 1 Singhe oil leaks. Supension performance ✓ 1 1 Seats Wear on front seats. ✓ 1 1 1 Seats Wear on front seats. ✓ 1			N							
Drivers don's el danaged. Left ront 3 mm Pront bumper danaged. Right front 3 mm Conditions During Body Inspection: Dry Right front 6 mm Under Carriage & Under Bonnet Inspection Comments Spare N/A Engine oil leaks. Systemsion performance / 0 0 Interior Comments Suspension performance / 0 0 0 Seats Wear on front seats. Verage Operation / 0	Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram								6 .	Ļ
Front bumper damaged. Right front 3 mm Index carriage & Under Bonnet Inspection: Dry Right rear 6 mm Under Carriage & Under Bonnet Inspection Comments Bught rear 6 mm Supension Supension 2 2 Under Carriage & Under Bonnet Inspection Comments Supension 2 2 Supension 4 2 2 2 Interior Comments Operation 4 2 2 2 Seats Wear on front seats. 9 2										
Conditions During Body Inspection: Dry Right rear 6 mm Inder Carriage & Under Bonnet Inspection Comments Spare 5 Suspension performance 2 0 Engine oil teaks. Stoering performance 2 0 <td colspan="6"></td> <td></td> <td></td> <td></td> <td>-</td>										-
Conditions During Body Inspection: Dry Right rear 6 mm Under Carriage & Under Bonnet Inspection Comments Suspension Suspension I		J								mm
Under Carriage & Under Bonnet Inspection Comments Spare N/A Engine oil leaks. Suspension performance ✓ 0 0 Interior Comments ✓ 0									5	mm
Under Carriage & Under Bonnet Inspection Comments Suspension Engine oil leaks. Suspension performance \$ I I Suspension performance \$ I I I Steering performance \$ I I I I Steering performance \$ I	Conditions During Body Inspection: Dry						-	6 mm		
Engine oil leaks. Suspension performance ✓							Spare	N/A		
Seering performance i i i Seering performance i i i Shock absorbers i i i Air Conditioning / Heater i i i Seats Wear on front seats. i i i i Carpets Average i i i i i Panels Average i										
Shock absorbers ✓	Engine oil l	eaks.						~		
Interior Comments Operation Image Image Seats Wear on front seats. Electrical / Accessories Head lights Image Image Carpets Average Image							Steering performance	~		
Interior Comments Operation ✓ Image Seats Wear on front seats. Head lights ✓ Image Carpets Average Indicators ✓ Image Dashboard Average Image Image </td <td colspan="7">Shock</td> <td>~</td> <td></td> <td></td>	Shock							~		
Interior Comments Wear on front seats. Seats Wear on front seats. Carpets Average Panels Average Dashboard Average Dashboard V Mean on front seats. V Dashboard V Mean on front seats. V Dashboard V Mean on front seats. V Mean on front seats. V Dashboard Average Mean on front seats. V							Air Conditioning / Heater			
Seats Wear on front seats. Carpets Average Panels Average Dashboard Average Dashboard Average Munder FL V Vindow winder FL V Vindow winder RL V Vindow vinder RL V Vindow vinder RL V Rear view mirrors V Read Conditions During Test Drive: Dry Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms: Kersing camera V Kersing camera V										
Seats Average Indicators Image Image Panels Average Image										
Carpets Average indicators ✓ Indicators Panels Average Dashboard warning lights ✓ Indicators Dashboard Average Wipers (front & rear) ✓ Indicators General Comments ✓ ✓ Indicators ✓ Indicators Petrol auto 325i Touring wagon. ✓ ✓ ✓ Indicators ✓ ✓ Thump in transmission when decelerating, suggest possibly mounts. ✓<	Seats	wear on fr	ont seats.				Head lights	~		
Panels Average Dashboard Dashboard warning lights ✓	Carpote	Average					Tail lights	~		
Particles Average Wipers (front & rear) V I Dashboard Average Window winder FL V I General Comments Vindow winder FR V I I Petrol auto 325i Touring wagon. Window winder RR V I I Rear view mirrors V I I I Readio (basic test only) V I I Road Conditions During Test Drive: Dry I I Engine Timing Mechanism: Timing Chain V I I Evidence of Cam Belt Replacement: Not Applicable Kms: Kms: I V							Indicators	~		
Dashboard Average Window winder FL ✓ I General Comments Window winder FR ✓ I Petrol auto 325i Touring wagon. Window winder RR ✓ I Number of keys ✓ I I Readio (basic test only) ✓ I I Road Conditions During Test Drive: Dry I I I Engine Timing Mechanism: Timing Chain ✓ I I Evidence of Cam Belt Replacement: Not Applicable Kms: Kms: I I	Panels	Average					Dashboard warning lights	~		
DashboardVIGeneral Comments Petrol auto 325i Touring wagon. Thump in transmission when decelerating, suggest possibly mounts.Window winder RRVIRear view mirrorsVIIRadio (basic test only)VIICD (basic test only)VIIRoad Conditions During Test Drive:DryCentral lockingVIEngine Timing Mechanism:Timing Chain Evidence of Cam Belt Replacement:Not ApplicableKms:Kms:I	Dashte	Average					Wipers (front & rear)	~		
General Comments Window winder RL Image: Comments Petrol auto 325i Touring wagon. Window winder RR Image: Comments Thump in transmission when decelerating, suggest possibly mounts. Image: Comments Image: Comments Rear view mirrors Image: Comments Image: Comments Image: Comments Rear view mirrors Image: Comments Image: Comments Image: Comments Radio (basic test only) Image: Comments Image: Comments Image: Comments Road Conditions During Test Drive: Dry Image: Comments Image: Comments Engine Timing Mechanism: Timing Chain Image: Comments Image: Comments Image: Comments Evidence of Cam Belt Replacement: Not Applicable Kms: Image: Comments Image: Comments Image: Comments							Window winder FL	~		
Petrol auto 325i Touring wagon. Thump in transmission when decelerating, suggest possibly mounts. Humber of keys Radio (basic test only) CD (basic tes		_					Window winder FR	~		
Thump in transmission when decelerating, suggest possibly mounts. Window Winder KK V I Rear view mirrors V I I Radio (basic test only) V I I CD (basic test only) V I I Number of keys 1 I I Read Conditions During Test Drive: Dry Central locking V I Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only) V I Evidence of Cam Belt Replacement: Not Applicable Kms: Kms: Sat. Nav. (basic test only) V I							Window winder RL	~		
Rear view mirrors ✓							Window winder RR	~		
CD (basic test only) ✓			, <u>.</u>	,			Rear view mirrors	~		
Number of keys 1 Road Conditions During Test Drive: Dry Central locking ✓ Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only) ✓ ✓ Evidence of Cam Belt Replacement: Not Applicable Kms: Kms: ✓ ✓							Radio (basic test only)	~		
Road Conditions During Test Drive: Dry Central locking V I Engine Timing Mechanism: Timing Chain Image: Sat. Nav. (basic test only) V Image: Sat. Nav. (basic test only) V Image: Sat. Nav. (basic test only) V Image: Sat. Nav. (basic test only)							CD (basic test only)	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms: Reversing camera							Number of keys	1		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms: Reversing camera V V	Road Con	ditions During Test	t Drive:	Dry			Central locking	~		
Evidence of Cam Belt Replacement: Not Applicable Kms: Reversing camera ✓				•			Remote locking	~		
	-	-	-	Chain			Sat. Nav. (basic test only)			~
Inspected by: Daryll Timms Date: 28 Nov 2024	Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Daryll Timms Date: 28 Nov 2024										
	Inspecte	d by: Daryll Timms					Date: 28 Nov 20	24		

Name: