

Report ID: 26,494,962 1 Version: 06 Jan 2025 Created:

| Make: | Lexus | Model: | IS250 | Body Style: | Sedan | 7Г | | Pass | Fail | N/A | |
|---|---------------------------|----------------------|------------------------|--|----------------------|------------|--|--------|------|-----|--|
| Year: | 2008 | Registration: | MSF834 | Reg Expiry: | 20 Aug 2025 | | Engine | | | | |
| WoF Expiry: | 06 May 2025 | Odometer: | 145,200 Kms | Good No: | 26494962 | | Oil level | | ~ | | |
| VIN: | 7AT0B00EX20067042 | Next Service: | way overdue | Service Histor | y: Yes | | Smoke & fumes | ~ | | | |
| | | | | | | 51 | Performance | ~ | | | |
| Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or | | | | | | . [| Noise | ~ | | | |
| diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | | Cooling System | | | | |
| | | | | | | | Coolant condition | ~ | | | |
| | S D | | | | S SC W | ٦٢ | Performance | ~ | | | |
| Key: | | -0 | | | 330 11 | | Radiator / Hoses (visual) | ~ | | | |
| S = scratch | | | | | | 15 | Transmission | | | | |
| D = dent R = rust | | | | | | | Operation | ~ | | | |
| PT = paint defe | ect NP | IT I | | $\left(\left \left(\right) \right\rangle \right)$ | 7014 | | Noise | ~ | | | |
| C = crack | | | | | | | Clutch | | | ~ | |
| P = pin dent | HIS | | | | 74114 | | CV joints | | | ~ | |
| * = decals SC 99 | | | | | | | Wheel bearings | ~ | | | |
| SC = stone chips | | | | | | | Brakes | | | | |
| W = significant scuffs | | | | | | | Performance | ~ | | | |
| Bodylog | action Commonts | Note: son | ne defects & blemishes | may not be disp | layed in the diagram | | Hand Brake | ~ | | | |
| Body Inspection Comments | | | | | | | Tyres (lowest observed tread depth of tyres) | | | | |
| Lhf inner wheel guard damaged. | | | | | | | Left front 7.0 mm | | | | |
| | | | | | | | Right front | | .0 | mm | |
| | | | | | | Jŀ | Left rear | | | mm | |
| Conditions During Body Inspection: Dry | | | | | | ٦ŀ | Right rear 6.0 | | | mm | |
| Conditions During Body Inspection: Dry | | | | | | ᆜ┠ | Spare Yes | | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | | Suspension | | | | |
| Testedless | | | () - :!!!· | | | | Suspension performance | ~ | | | |
| lested batt | ery and failed. Oil level | approximately 1 | 2. OII leak | | | | Steering performance | ~ | | | |
| | | | | | | | Shock absorbers | ~ | | | |
| | | | | | | | Air Conditioning / Heater | - | | | |
| | | | | | | | Operation | | ~ | | |
| Interior Comments | | | | | | E | Electrical / Accessories | | | | |
| Seats | Seats marks | | | | | | Head lights | ~ | | | |
| | | | | | | | Tail lights | ~ | | | |
| Carpets | Average | | | | | | Indicators | ~ | | | |
| Panels | scratches | scuffs marks knic | kc | | | | Dashboard warning lights | ~ | | | |
| | | | | | | | Wipers (front & rear) | ~ | | | |
| Dashboa | rd scratches | sticky cracking | | | | | Window winder FL | ~ | | | |
| | | | | | | <u>⊣</u> ⊦ | Window winder FR | ~ | | | |
| General C | <u>Comments</u> | | | | | | Window winder RL | ~ | | | |
| Air conditioning nw. | | | | | | | Window winder RR | ~ | | | |
| | | | | | | | Rear view mirrors | ~ | | | |
| | | | | | | | Radio (basic test only) | ~ | | | |
| | | | | | | | CD (basic test only) | ~ | | | |
| | | | | | | _ ŀ | Number of keys | 1 | I | 1 | |
| Road Conditions During Test Drive: Dry | | | | | | | Central locking | · ✓ | | | |
| | | | יזע | | | ┛┠ | Remote locking | • • | | | |
| Engine Ti | ming Mechanism: | Timing | Chain | | |] | Sat. Nav. (basic test only) | - | | ~ | |
| Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | | Reversing camera | | ~ | - | |
| | • | - | | | | | | | • | L | |
| Inspected by: Gary Adams Date: 19 Dec 2024 | | | | | | | | | | | |
| | | | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: