

Report ID: 26,371,215 Version: 4 24 Oct 2024 Created:

| Make: | Hyundai | Model: | lload | Body Style: | Van | | Pass | Fail | N/A |
|--|------------------------|---------------|------------------------|-----------------|----------------------|--|------|----------|-----|
| Year: | 2016 | Registration: | KDT465 | Reg Expiry: | 31 Jan 2025 | Engine | | · un | , |
| | 18 Oct 2025 | Odometer: | 214,694 Kms | Good No: | 26371215 | Oil level | ~ | | |
| VIN: | KMFWBX7KMHU8591 | | | Service Histor | | Smoke & fumes | ~ | | |
| | | | 225,000 km | | | Performance | ~ | | |
| | port is not a warranty | | | | | Noise | | ~ | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends | | | | | | Cooling System | | | |
| a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Coolant condition | | | |
| | | _ | | | | Performance | ~ | | |
| Key: | | -0 | SD SP | | | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent | s sc | | | 1 - L | BIDR | Operation | ~ | | |
| R = rust | | | | 10 | JHIH | Noise | ~ | | |
| PT = paint def C = crack | ect M | | | + | D | Clutch | ~ | | ~ |
| P = pin dent | Ho | KI | | | JUII —— | CV joints | ~ | | |
| * = decals | R SC PIC | | | AL- | ETTR PW | Wheel bearings | | | |
| SC = stone chips | | | | | | | | | |
| W = significant scuffs D R SC | | | | | | Brakes | | | 1 |
| | | Nata | | | | Performance | ~ | | |
| Body Insp | pection Comments | Note: son | ne defects & blemishes | may not be disp | layed in the diagram | Hand Brake | | <u> </u> | Ļ |
| L/H filler panel scuffs. | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| Front bumper refit. R/F seat belt fraying. | | | | | | Left front | 5 | .0 | mm |
| | , , | | | | | Right front | 5 | .0 | mm |
| | | | | | | Left rear | 5 | .0 | mm |
| Conditions During Body Inspection: | | | | | | Right rear 5.0 mm | | | mm |
| | | | | | | Spare Yes | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | 1 | | |
| RWD. Excessive oil leak underside. | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | 1 | - |
| | | | | | | Operation 🖌 | | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Poor | | | | | Head lights | ~ | | |
| Carpote | Good | | | | | Tail lights | ~ | | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| Dest | rd Good | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | iu | | | | | Window winder FL | ~ | | |
| _ | | | | | | Window winder FR | ~ | | |
| <u>General Comments</u> | | | | | | Window winder RL | | | ~ |
| Centre seat stuck won't retract. Exhaust has air leak sound underload suspect coming from manifold or mid-pipe. | | | | | | Window winder RR | | | ~ |
| | | | | P P | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | | | ~ |
| | | | | | | Number of keys | 2 | | |
| Road Conditions During Test Drive: Dry Central lo | | | | | | | ~ | | |
| , | | | | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | ~ | | |
| | | | | | | | | | |
| Inspected by: Imraan Bryant Date: 22 Oct 2024 | | | | | | | | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: