Basic Vehicle Condition Guide

Report ID: 17,999,721
Version: 2
Created: 13 Aug 2024

Make:	Holden	**Model:**	Colorado	**Body Style:**	Utility
Year:	2019	**Registration:**	MDZ796	**Reg Expiry:**	17 Sep 2024
WoF Expiry:	30 Jun 2025	**Odometer:**	197,709 Kms	**Good No:**	17999721
VIN:	MMU148LK0LH60144	**Next Service:**	202,000kms	**Service History:**	No

Note: This report is not a warranty
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key:
S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs



Note: some defects & blemishes may not be displayed in the diagram

Body Inspection Comments

Bonnet stone guard is cracked.
Left shill paint flaking.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments

Seats	Average
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

Driver's seat base bad is worn,torn.
Driving required as exhaust filter cleaning alert is ON.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt
Evidence of Cam Belt Replacement: Yes Kms: 154,000

	Pass	Fail	N/A
Engine			
Oil level	✔		
Smoke & fumes	✔		
Performance	✔		
Noise	✔		
Cooling System			
Coolant condition	✔		
Performance	✔		
Radiator / Hoses (visual)	✔		
Transmission			
Operation	✔		
Noise	✔		
Clutch			✔
CV joints	✔		
Wheel bearings	✔		
Brakes			
Performance	✔		
Hand Brake	✔		
Tyres (lowest observed tread depth of tyres)			
Left front	5 mm		
Right front	7 mm		
Left rear	6 mm		
Right rear	5 mm		
Spare	Yes		
Suspension			
Suspension performance	✔		
Steering performance	✔		
Shock absorbers	✔		
Air Conditioning / Heater			
Operation	✔		
Electrical / Accessories			
Head lights	✔		
Tail lights	✔		
Indicators	✔		
Dashboard warning lights	✔		
Wipers (front & rear)	✔		
Window winder FL	✔		
Window winder FR	✔		
Window winder RL	✔		
Window winder RR	✔		
Rear view mirrors	✔		
Radio (basic test only)	✔		
CD (basic test only)			✔
Number of keys	2		
Central locking	✔		
Remote locking	✔		
Sat. Nav. (basic test only)	✔		
Reversing camera	✔		

Inspected by: Yuki Itohara Date: 13 Aug 2024

I have read and understood this condition guide. Name: ..... Signature: .....