Basic Vehicle Condition Guide

Report ID: 23,021,496
Version: 2
Created: 15 Nov 2024

Make:	Mazda	**Model:**	323	**Body Style:**	Hatchback
Year:	1999	**Registration:**	XZ3529	**Reg Expiry:**	15 Mar 2025
WoF Expiry:	13 Nov 2024	**Odometer:**	117,323 Kms	**Good No:**	23021496
VIN:	JM0BJ10M100103810	**Next Service:**	120000km	**Service History:**	No

Note: This report is not a warranty
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key:
S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs



Note: some defects & blemishes may not be displayed in the diagram

Body Inspection Comments

Dent in passengers side rocker panel.
Rust in Left rear window frame.
Surface rust starting in rest of window frames.

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Corrosion underneath vehicle.
Oil seepage .

Interior Comments

Seats	Good
Carpets	Average
Panels	Average
Dashboard	Good

General Comments

Vehicle drove ok.
Rough idle.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt
Evidence of Cam Belt Replacement: Yes Kms: 100,370

	Pass	Fail	N/A
Engine			
Oil level	✔		
Smoke & fumes	✔		
Performance	✔		
Noise	✔		
Cooling System			
Coolant condition	✔		
Performance	✔		
Radiator / Hoses (visual)	✔		
Transmission			
Operation	✔		
Noise	✔		
Clutch			✔
CV joints	✔		
Wheel bearings	✔		
Brakes			
Performance	✔		
Hand Brake	✔		
Tyres (lowest observed tread depth of tyres)			
Left front	8 mm		
Right front	8 mm		
Left rear	7 mm		
Right rear	7 mm		
Spare	Yes		
Suspension			
Suspension performance	✔		
Steering performance	✔		
Shock absorbers	✔		
Air Conditioning / Heater			
Operation	✔		
Electrical / Accessories			
Head lights	✔		
Tail lights	✔		
Indicators	✔		
Dashboard warning lights	✔		
Wipers (front & rear)	✔		
Window winder FL	✔		
Window winder FR	✔		
Window winder RL	✔		
Window winder RR	✔		
Rear view mirrors	✔		
Radio (basic test only)		✔	
CD (basic test only)			✔
Number of keys	1		
Central locking	✔		
Remote locking	✔		
Sat. Nav. (basic test only)			✔
Reversing camera			✔

Inspected by: Aaron Johnson Date: 15 Nov 2024

I have read and understood this condition guide. Name: ..... Signature: .....