# Turners

## Basic Vehicle Condition Guide

Report ID: 25,089,451
Version: 1
Created: 14 Nov 2024

| | | | |
|---|---|---|---|
| **Make:** Mitsubishi | **Model:** Triton | **Body Style:** Utility | |
| **Year:** 2020 | **Registration:** MTR886 | **Reg Expiry:** 22 Mar 2025 | |
| **WoF Expiry:** 02 May 2025 | **Odometer:** 109,804 Kms | **Good No:** 25089451 | |
| **VIN:** MMAJLKL10LH011798 | **Next Service:** 123,000 kms | **Service History:** Yes | |

**Note: This report is not a warranty**
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**
S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs

Diagram labels: SC, P SC, SC, SC, PT C SC, SC, SC, SC, D, W, SC, P, PT P, D

Note: some defects & blemishes may not be displayed in the diagram

### Body Inspection Comments
Stone chips in windscreen, minor dents right cab corner
Right front step plate worn,

| Conditions During Body Inspection: | Wet |
|---|---|

### Under Carriage & Under Bonnet Inspection Comments

### Interior Comments

| | |
|---|---|
| Seats | Good |
| Carpets | Good |
| Panels | Good |
| Dashboard | chips in centre console |

### General Comments

| Road Conditions During Test Drive: | Wet |
|---|---|

| Engine Timing Mechanism: | Timing Chain |
|---|---|
| Evidence of Cam Belt Replacement: | Not Applicable | Kms: |

Inspected by: Dean Sinclair | Date: 14 Nov 2024

| | Pass | Fail | N/A |
|---|---|---|---|
| **Engine** | | | |
| Oil level | ✔ | | |
| Smoke & fumes | ✔ | | |
| Performance | ✔ | | |
| Noise | ✔ | | |
| **Cooling System** | | | |
| Coolant condition | ✔ | | |
| Performance | ✔ | | |
| Radiator / Hoses (visual) | ✔ | | |
| **Transmission** | | | |
| Operation | ✔ | | |
| Noise | ✔ | | |
| Clutch | | | ✔ |
| CV joints | ✔ | | |
| Wheel bearings | ✔ | | |
| **Brakes** | | | |
| Performance | ✔ | | |
| Hand Brake | ✔ | | |
| **Tyres** (lowest observed tread depth of tyres) | | | |
| Left front | 9 | mm | |
| Right front | 4.5 | mm | |
| Left rear | 4.5 | mm | |
| Right rear | 4.5 | mm | |
| Spare | Yes | | |
| **Suspension** | | | |
| Suspension performance | ✔ | | |
| Steering performance | ✔ | | |
| Shock absorbers | ✔ | | |
| **Air Conditioning / Heater** | | | |
| Operation | ✔ | | |
| **Electrical / Accessories** | | | |
| Head lights | ✔ | | |
| Tail lights | ✔ | | |
| Indicators | ✔ | | |
| Dashboard warning lights | ✔ | | |
| Wipers (front & rear) | ✔ | | |
| Window winder FL | ✔ | | |
| Window winder FR | ✔ | | |
| Window winder RL | ✔ | | |
| Window winder RR | ✔ | | |
| Rear view mirrors | ✔ | | |
| Radio (basic test only) | ✔ | | |
| CD (basic test only) | | | ✔ |
| Number of keys | 2 | | |
| Central locking | ✔ | | |
| Remote locking | ✔ | | |
| Sat. Nav. (basic test only) | | | ✔ |
| Reversing camera | ✔ | | |

I have read and understood this condition guide.　Name: ......................................................　Signature: ....................................