Basic Vehicle Condition Guide

Report ID: 26,363,179
Version: 1
Created: 21 Oct 2024

Make:	Subaru	**Model:**	Impreza	**Body Style:**	Hatchback
Year:	2008	**Registration:**	MFC862	**Reg Expiry:**	13 Dec 2024
WoF Expiry:	02 Nov 2024	**Odometer:**	163,059 Kms	**Good No:**	26363179
VIN:	7AT0GF09X19005471	**Next Service:**	172,000	**Service History:**	No

Note: This report is not a warranty
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key:
S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs



Note: some defects & blemishes may not be displayed in the diagram

Body Inspection Comments

Front bumper different colour to vehicle, Headlamps cloudy, LH side skirt coming off, Structural dent in LH sill & "C" pillar, Paint faded on rear spoiler,

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

All wheel drive, All rear differential mounts broken, Front lower radiator cross member bent, LH rocker cover leaking, Coolant very over full.
Aftermarket exhaust fitted, Aftermarket pod filter fitted

Interior Comments

Seats	Average
Carpets	Average
Panels	Good
Dashboard	Good

General Comments

Centre interior light not working, All seats stained, Drivers side fuse box cover missing, Centre console lid broken, Rear vision mirror delaminating, Air-con not working, Front & rear brake pulse, Clutch slipping

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt
Evidence of Cam Belt Replacement: Yes Kms: 109,752

	Pass	Fail	N/A
Engine			
Oil level	✔		
Smoke & fumes	✔		
Performance	✔		
Noise	✔		
Cooling System			
Coolant condition		✔	
Performance	✔		
Radiator / Hoses (visual)	✔		
Transmission			
Operation	✔		
Noise	✔		
Clutch		✔	
CV joints	✔		
Wheel bearings	✔		
Brakes			
Performance		✔	
Hand Brake	✔		
Tyres (lowest observed tread depth of tyres)			
Left front	5 mm		
Right front	5 mm		
Left rear	6 mm		
Right rear	6 mm		
Spare	Yes		
Suspension			
Suspension performance	✔		
Steering performance	✔		
Shock absorbers	✔		
Air Conditioning / Heater			
Operation		✔	
Electrical / Accessories			
Head lights	✔		
Tail lights	✔		
Indicators	✔		
Dashboard warning lights	✔		
Wipers (front & rear)	✔		
Window winder FL	✔		
Window winder FR	✔		
Window winder RL	✔		
Window winder RR	✔		
Rear view mirrors	✔		
Radio (basic test only)	✔		
CD (basic test only)	✔		
Number of keys	1		
Central locking	✔		
Remote locking	✔		
Sat. Nav. (basic test only)			✔
Reversing camera			✔

Inspected by: Andre Richardson Date: 21 Oct 2024

I have read and understood this condition guide. Name: ..... Signature: .....