Basic Vehicle Condition Guide

Report ID: 26,423,715
Version: 1
Created: 25 Nov 2024

Make:	Toyota	**Model:**	Landcruiser Prado	**Body Style:**	Wagon
Year:	1996	**Registration:**	ZL8890	**Reg Expiry:**	04 Feb 2025
WoF Expiry:	30 Jan 2025	**Odometer:**	406,609 Kms	**Good No:**	26423715
VIN:	7A8H60H0700025415	**Next Service:**	overdue	**Service History:**	Yes

Note: This report is not a warranty
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key:
S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs



Note: some defects & blemishes may not be displayed in the diagram

Body Inspection Comments

No check strap drivers door. Centre arm rest broken. Rhr window broken and wedged, lhr very slow. Rear door hinges worn. Stone chips in front screen. Stone chips in headlights

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Tested battery and failed. Brake fluid low . Requires front brakes. Oil leaks. Cracked centre muffler. Air filter housing cable tied in place. Oil level on minimum level

Interior Comments

Seats	marks
Carpets	Average
Panels	scratches scuffs marks
Dashboard	scratches

General Comments

Timing belt light on. Rh mirror glass glued in place. Air conditioning belt missing. Wipers smear and no rear washer. Rh brake light nw.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt
Evidence of Cam Belt Replacement: Yes Kms: 391,449

	Pass	Fail	N/A
Engine			
Oil level		✔	
Smoke & fumes		✔	
Performance	✔		
Noise	✔		
Cooling System			
Coolant condition	✔		
Performance	✔		
Radiator / Hoses (visual)	✔		
Transmission			
Operation	✔		
Noise	✔		
Clutch			✔
CV joints	✔		
Wheel bearings	✔		
Brakes			
Performance		✔	
Hand Brake	✔		
Tyres (lowest observed tread depth of tyres)			
Left front	5.0 mm		
Right front	6.0 mm		
Left rear	5.0 mm		
Right rear	5.0 mm		
Spare	Yes		
Suspension			
Suspension performance	✔		
Steering performance	✔		
Shock absorbers	✔		
Air Conditioning / Heater			
Operation		✔	
Electrical / Accessories			
Head lights	✔		
Tail lights		✔	
Indicators	✔		
Dashboard warning lights		✔	
Wipers (front & rear)		✔	
Window winder FL	✔		
Window winder FR	✔		
Window winder RL		✔	
Window winder RR		✔	
Rear view mirrors		✔	
Radio (basic test only)	✔		
CD (basic test only)	✔		
Number of keys	2		
Central locking	✔		
Remote locking			✔
Sat. Nav. (basic test only)			✔
Reversing camera			✔

Inspected by: Gary Adams Date: 14 Nov 2024

I have read and understood this condition guide. Name: ..... Signature: .....