# Turners

## Basic Vehicle Condition Guide

Report ID: 26,461,235
Version: 4
Created: 12 Dec 2024

| | | |
|---|---|---|
| **Make:** Toyota | **Model:** Hiace | **Body Style:** Van |
| **Year:** 2009 | **Registration:** LPF713 | **Reg Expiry:** 12 Feb 2025 |
| **WoF Expiry:** 19 Jan 2025 | **Odometer:** 255,180 Kms | **Good No:** 26461235 |
| **VIN:** 7AT0H60FX18009340 | **Next Service:** 0km | **Service History:** No |

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**

S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs

Diagram labels: W, S P, S, S, S D, R PT, S D R PT, S P, S P, W, S D P, S D SC, W, S R P

Note: some defects & blemishes may not be displayed in the diagram

### Body Inspection Comments

L/H wing mirror damaged.
Tail lights scratched&cracked.

### Conditions During Body Inspection: Dry

### Under Carriage & Under Bonnet Inspection Comments

RWD.
Oil leak underside.

### Interior Comments

| | |
|---|---|
| Seats | Poor |
| Carpets | Poor |
| Panels | Poor |
| Dashboard | Poor |

### General Comments

Hi stop light cracked not working.
Radio not working properly.
Front wipers rusty.

### Road Conditions During Test Drive: Dry

**Engine Timing Mechanism:** Timing Chain

**Evidence of Cam Belt Replacement:** Not Applicable     **Kms:**

| | Pass | Fail | N/A |
|---|---|---|---|
| **Engine** | | | |
| Oil level | ✔ | | |
| Smoke & fumes | ✔ | | |
| Performance | ✔ | | |
| Noise | ✔ | | |
| **Cooling System** | | | |
| Coolant condition | ✔ | | |
| Performance | ✔ | | |
| Radiator / Hoses (visual) | ✔ | | |
| **Transmission** | | | |
| Operation | ✔ | | |
| Noise | ✔ | | |
| Clutch | | | ✔ |
| CV joints | ✔ | | |
| Wheel bearings | ✔ | | |
| **Brakes** | | | |
| Performance | ✔ | | |
| Hand Brake | ✔ | | |
| **Tyres** (lowest observed tread depth of tyres) | | | |
| Left front | 7.0 | | mm |
| Right front | 8.0 | | mm |
| Left rear | 6.0 | | mm |
| Right rear | 6.0 | | mm |
| Spare | Yes | | |
| **Suspension** | | | |
| Suspension performance | ✔ | | |
| Steering performance | ✔ | | |
| Shock absorbers | ✔ | | |
| **Air Conditioning / Heater** | | | |
| Operation | ✔ | | |
| **Electrical / Accessories** | | | |
| Head lights | ✔ | | |
| Tail lights | | ✔ | |
| Indicators | ✔ | | |
| Dashboard warning lights | ✔ | | |
| Wipers (front & rear) | ✔ | | |
| Window winder FL | | ✔ | |
| Window winder FR | ✔ | | |
| Window winder RL | | | ✔ |
| Window winder RR | | | ✔ |
| Rear view mirrors | ✔ | | |
| Radio (basic test only) | | ✔ | |
| CD (basic test only) | | | ✔ |
| Number of keys | 2 | | |
| Central locking | ✔ | | |
| Remote locking | ✔ | | |
| Sat. Nav. (basic test only) | | | ✔ |
| Reversing camera | ✔ | | |

**Inspected by:** Imraan Bryant

**Date:** 06 Dec 2024

I have read and understood this condition guide.     Name: ...........................................................     Signature: .....................................