

Report ID: 24,417,275 Version: 2 03 May 2024 Created:

Make:	Toyota	Model:	Sienta	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2016	Registration:		Reg Expiry:		Engine	1		
WoF Expiry:		Odometer:	47,636 Kms	Good No:	24417275	Oil level	~		
VIN:	7AT0H64YX23040429	Next Service:		Service Histor	-	Smoke & fumes	~		
			- ,		•	Performance	~		
	port is not a warranty		с I II			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	GIE			The		Operation	~		
R = rust				1 M	JHIH	Noise	~		
PT = paint defe C = crack				+		Clutch	•		~
P = pin dent	Ho					CV joints	~		~
* = decals	- MIK			AL		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance			
		Noto: con	he defects & blemishes		alayod in the diagram		~		
Body Insp	pection Comments	Note. son	le délects & bieffisile:	s may not be dis	Dayed in the diagram	Hand Brake		- f h m	•
						Tyres (lowest observed tread depth of tyres)			
						Left front			mm
						Right front			mm
						Left rear	5.5 mm		
Conditions During Body Inspection: Wet						Right rear	5.8 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage & onder bor	mermspectic	in comments			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Interior Comments Good						Electrical / Accessories			
Seats	GUUU					Head lights	~		
Carpets	Good					Tail lights	~		
	Card					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	2		
						Rear view mirrors	2		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Wet Central locking							~		
						Remote locking	~		
-	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		
Inspected by: Hoani Saunders Date: 02 May 2024									

I have read and understood this condition guide.

Name:

Signature: