



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	24,417,345
Version:	1
Created:	11 Dec 2023

Make:	Toyota	Body Style:	
Model:	Estima	VIN:	
Year:	2010	Odometer:	82,928 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	<input checked="" type="checkbox"/>	Cooling System		55	Coolant Condition	<input checked="" type="checkbox"/>	Exterior	
1	Battery	<input checked="" type="checkbox"/>	31	Reversing Camera	<input type="checkbox"/>	56	Performance	<input checked="" type="checkbox"/>	78	Under Carriage	Good
2	Headlights	<input checked="" type="checkbox"/>	32	USB Port	<input type="checkbox"/>	57	Radiator/Hoses (visual)	<input checked="" type="checkbox"/>	79	Sun Roof Operation	<input type="checkbox"/>
3	Tail Lights	<input checked="" type="checkbox"/>	33	Window Lock Switch	<input checked="" type="checkbox"/>	Suspension		80	Front Windscreen (no chips)	Good	
4	High Stop Light	<input checked="" type="checkbox"/>	Transmission and Drive		58	Suspension Performance	<input checked="" type="checkbox"/>	81	Back Windscreen (no chips)	Good	
5	Front Right Indicators	<input checked="" type="checkbox"/>	34	Operation	<input checked="" type="checkbox"/>	59	Steering Performance	<input checked="" type="checkbox"/>	82	Side Windows (no chips)	Good
6	Front Left Indicators	<input checked="" type="checkbox"/>	35	Noise	<input checked="" type="checkbox"/>	60	Shock Absorbers	<input checked="" type="checkbox"/>	83	Front Wiper Blades	Good
7	Rear Right Indicators	<input checked="" type="checkbox"/>	36	Clutch	<input type="checkbox"/>	Wheels and Tyres		84	Rear Wiper Blade	Good	
8	Rear Left Indicators	<input checked="" type="checkbox"/>	37	CV Joints	<input checked="" type="checkbox"/>	61	Left Front	7.5 mm	85	R/H Mirror	Good
9	Reversing Lights	<input checked="" type="checkbox"/>	38	Wheel Bearing	<input checked="" type="checkbox"/>	62	Right Front	7.5 mm	86	L/H Mirror	Good
10	Rear Reflectors	<input checked="" type="checkbox"/>	39	Wheel Balance	<input checked="" type="checkbox"/>	63	Left Rear	6 mm	87	L/F Guard	Good
11	Hazard Lights	<input checked="" type="checkbox"/>	40	Gearbox (Manual)	<input type="checkbox"/>	64	Right Rear	6 mm	88	R/F Guard	Good
12	Courtesy Lights	<input checked="" type="checkbox"/>	41	Engine Timing	Timing Chain	65	Spare	N/A	89	L/H Doors	Good
13	Dashboard Lights	<input checked="" type="checkbox"/>	42	Evidence of Cam Belt Replacement	Not Applicable	66	Tools	<input checked="" type="checkbox"/>	90	R/H Doors	Good
14	Dashboard Dimmer Switch	<input checked="" type="checkbox"/>	43	Replaced at (odometer reading)		Interior		91	L/H Sill	Good	
15	Number Plate Light	<input checked="" type="checkbox"/>	Brakes		67	AC Operation	<input checked="" type="checkbox"/>	92	R/H Sill	Good	
16	Dashboard Warning Lights	<input checked="" type="checkbox"/>	44	Front Brakes	<input checked="" type="checkbox"/>	68	Heater Fan	<input checked="" type="checkbox"/>	93	Boot/Tail Gate	Good
17	Speedo	<input checked="" type="checkbox"/>	45	Rear Brakes	<input checked="" type="checkbox"/>	69	Seatbelts	<input checked="" type="checkbox"/>	94	Front Bumper	Good
18	Odometer	<input checked="" type="checkbox"/>	46	Handbrake	<input checked="" type="checkbox"/>	70	Horn	<input checked="" type="checkbox"/>	95	Rear Bumper	Good
19	Rev Counter	<input type="checkbox"/>	Keys and Locking		71	Seat Heaters	<input type="checkbox"/>	96	Roof	Good	
20	Fuel Gauge	<input checked="" type="checkbox"/>	47	Central Locking	<input checked="" type="checkbox"/>	72	Sun Visors	<input checked="" type="checkbox"/>	97	Bonnet	Good
21	Wipers Front/Rear	<input checked="" type="checkbox"/>	48	Remote Locking	<input checked="" type="checkbox"/>	73	Sun Visors Lights/Mirrors	<input checked="" type="checkbox"/>	98	Fuel Cap	<input checked="" type="checkbox"/>
22	Window Opener FL	<input checked="" type="checkbox"/>	49	Number of Keys	2	74	Seats	Good	99	Mud Flaps	<input checked="" type="checkbox"/>
23	Window Opener FR	<input checked="" type="checkbox"/>	Engine		75	Carpets	Good	100	WOF	<input checked="" type="checkbox"/>	
24	Window Opener RL	<input checked="" type="checkbox"/>	50	Oil Level	<input checked="" type="checkbox"/>	76	Panels	Good			
25	Window Opener RR	<input checked="" type="checkbox"/>	51	Smokes and Fumes	<input checked="" type="checkbox"/>	77	Dashboard	Good			
26	Rear View Mirrors	<input checked="" type="checkbox"/>	52	Performance	<input checked="" type="checkbox"/>						
27	Radio (Basic Test Only)	<input checked="" type="checkbox"/>	53	Noise	<input checked="" type="checkbox"/>						
28	CD (Basic Test Only)	<input checked="" type="checkbox"/>	54	Starter Motor	<input checked="" type="checkbox"/>						
29	Boot Open Switch	<input checked="" type="checkbox"/>									

Turners Certification Key:
✓ = Pass
✗ = Fail
• = Not applicable for this vehicle

Inspected by:	Dean Sinclair	Date:	11 Dec 2023
I have read and understood this condition guide:			
Name:		Signature:	