



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	24,486,003
Version:	1
Created:	24 Jan 2024

Make:	Mercedes-Benz	Body Style:	Hatchback
Model:	B180	VIN:	WDD2462422J020338
Year:	2012	Odometer:	22,134 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good			
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation		•					
2	Headlights	✓	32	USB Port	✓	57	Radiator/Hoses (visual)	✓	80	Front Windscreen (no chips)	Good						
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓	81	Back Windscreen (no chips)	Good				
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓	59	Steering Performance	✓	82	Side Windows (no chips)	Good				
5	Front Right Indicators	✓	35	Noise	✓	60	Shock Absorbers	✓	83	Front Wiper Blades	Good						
6	Front Left Indicators	✓	36	Clutch	•	Wheels and Tyres		61	Left Front	6.0	mm	84	Rear Wiper Blade	Good			
7	Rear Right Indicators	✓	37	CV Joints	✓	62	Right Front	6.0	mm	63	Left Rear	6.0	mm	85	R/H Mirror	Good	
8	Rear Left Indicators	✓	38	Wheel Bearing	✓	64	Right Rear	6.0	mm	65	Spare	No	86	L/H Mirror	Good		
9	Reversing Lights	✓	39	Wheel Balance	✓	66	Tools	✗	87	L/F Guard	Good						
10	Rear Reflectors	✓	40	Gearbox (Manual)	•	Interior		67	AC Operation	✓	88	R/F Guard	Good				
11	Hazard Lights	✓	41	Engine Timing	Timing Chain	68	Heater Fan	✓	69	Seatbelts	✓	89	L/H Doors	Good			
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	70	Horn	✓	71	Seat Heaters	•	90	R/H Doors	Good			
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	91	L/H Sill	Good			
14	Dashboard Dimmer Switch	✓	Brakes		44	Front Brakes	✓	74	Seats	Average	75	Carpets	Average	92	R/H Sill	Good	
15	Number Plate Light	✓	45	Rear Brakes	✓	46	Handbrake	✓	76	Panels	Average	77	Dashboard	Average	93	Boot/Tail Gate	Good
16	Dashboard Warning Lights	✓	Keys and Locking		47	Central Locking	✓	78	Seats	Average	79	Carpets	Average	94	Front Bumper	Good	
17	Speedo	✓	48	Remote Locking	✓	49	Number of Keys	2	80	Panels	Average	81	Dashboard	Average	95	Rear Bumper	Good
18	Odometer	✓	Engine		50	Oil Level	✓	82	Seats	Average	83	Carpets	Average	96	Roof	Good	
19	Rev Counter	✓	51	Smokes and Fumes	✓	52	Performance	✓	84	Panels	Average	85	Dashboard	Average	97	Bonnet	Good
20	Fuel Gauge	✓	53	Noise	✓	54	Starter Motor	✓	86	Dashboard	Average	87	Seats	Average	98	Fuel Cap	✓
21	Wipers Front/Rear	✓							88	Seats	Average	89	Carpets	Average	99	Mud Flaps	✓
22	Window Opener FL	✓							89	Panels	Average	90	Dashboard	Average	100	WOF	✓
23	Window Opener FR	✓							91	Seats	Average						
24	Window Opener RL	✓							92	Panels	Average						
25	Window Opener RR	✓							93	Dashboard	Average						
26	Rear View Mirrors	✓							94	Seats	Average						
27	Radio (Basic Test Only)	✓							95	Panels	Average						
28	CD (Basic Test Only)	•							96	Dashboard	Average						
29	Boot Open Switch	✓							97	Seats	Average						

Turners Certification Key:
✓ = Pass
✗ = Fail
• = Not applicable for this vehicle

Inspected by:	Greg Morgan	Date:	17 Jan 2024
I have read and understood this condition guide:			
Name:		Signature:	