

Report ID: 25,500,055 Version: 5 11 Mar 2024 Created:

	Subaru	Model:	Impreza	Body Style:	Wagon		Pass	Fail	N/A
	2015	Registration:	preza	Reg Expiry:		Engine			
WoF Expiry: 2		Odometer:	73,530 Kms	Good No:	25500055	Oil level	~		
		Next Service:		Service Histor		Smoke & fumes	~		<u> </u>
/	74100105724050251		03,327 Km		. 110	Performance	~		
	ort is not a warranty					Noise	~		
	a guide only. Conside						V		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			<u> </u>
						Coolant condition	~		
Key:	SC		S S			Performance	~		<u> </u>
S = scratch	R	(0)	<u>È</u>	105	~	Radiator / Hoses (visual)	~		
D = dent	Alt				ALL SC	Transmission			
R = rust	sc 96			$\langle \rangle \rangle$	SHIK	Operation	~		
PT = paint defec	ct N					Noise	~		<u> </u>
C = crack]]]]] 🖳	Clutch			~
P = pin dent * = decals	sc dl			SI_	18445	CV joints	~		
SC = stone chips	C TE	10		10	E SC	Wheel bearings	~		
W = significant scuffs						Brakes			
	SC	\sim	S S		S	Performance	~		
Body Inspe	ection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
<u>2007 aspector connerts</u>						Tyres (lowest observed tread depth of tyres)			
						Left front	ront 5.0 n		
						Right front	5	.0	mm
						Left rear	7	.0	mm
Conditions During Body Inspection: Dry						Right rear	7.0 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
FWD.						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	v		
Air Condition							•		L
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Seats						Tail lights	~		
Carpets	Good								
	Good						~		
Panels						Dashboard warning lights	V		
Dashboard	d Good					Wipers (front & rear)	~		
						Window winder FL	~		<u> </u>
General Co	omments					Window winder FR	~		<u> </u>
						Window winder RL	~		<u> </u>
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)		~	<u> </u>
						CD (basic test only)		~	
Numb						Number of keys	2	1	1
Road Conditions During Test Drive: Dry							~		
	·	 :				Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)								~	
Evidence o	of Cam Belt Replace	ement: N	lot Applicable	Kms:		Reversing camera			~
								•	
Inspected by: Todd Cullum Date: 07 Mar 2024									

I have read and understood this condition guide.

Name:

Signature: