

Basic Vehicle Condition Guide

Report ID: 19,381,255


Version: 1

Created: 21 Oct 2024

Make: Model: Hyundai Staria **Body Style:** People Mover Year: 2022 Registration: PDL183 Reg Expiry: 29 Mar 2025 Good No: WoF Expiry: **Odometer:** 30 Mar 2025 92,927 Kms 19381255 VIN: KMHYC811SNU02248 Next Service: 96,000kms **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

8 seater

Paint shrink on tail gate.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Rear fog light is not operating.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Yuki Itohara Date: 18 Oct 2024

Name:

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	<i>y y</i>			
Performance	~			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission	•			
Operation	~			
Noise	V			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread	d depth	of tyre	es)	
Left front	8.0		mm	
Right front	4.0		mm	
Left rear	5	.0	mm	
Right rear	5.0		mm	
Spare	Yes			
Suspension				
Suspension performance	~			
Steering performance	<i>V</i>			
Shock absorbers	~			
Air Conditioning / Heater	ı		ı	
Operation 🗸				
Electrical / Accessories	l			
Head lights	~			
Tail lights	~			
Indicators	~			
Dashboard warning lights	~			
Wipers (front & rear)	\(\times \)			
Window winder FL	~			
Window winder FR	~			
Window winder RL			~	
Window winder RR			~	
Rear view mirrors	~		<u> </u>	
Radio (basic test only)	~			
CD (basic test only)			~	
Number of keys	2		<u> </u>	
Central locking	~			
Remote locking	~			
Sat. Nav. (basic test only)	~			
Reversing camera	~			
Lieversing cumera				

Signature: