

Drv

<u> </u>		Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments		Suspension			
		Suspension performance	~		
		Steering performance	~		
		Shock absorbers	V		
		Air Conditioning / Heater			
		Operation	~		
Interior Comments		Electrical / Accessories			
Seats	Good	Head lights	~		
Carpets	Good	Tail lights	~		
		Indicators	~		
Panels	Good	Dashboard warning lights	~		
Dashboard	Good	Wipers (front & rear)	~		
		Window winder FL	~		
		Window winder FR	~		
General Comments		Window winder RL			~
		Window winder RR			~
		Rear view mirrors	~		
		Radio (basic test only)	~		
		CD (basic test only)			~
	Number of keys	3			
Road Conditions During Test Drive: Dry		Central locking	~		
		Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:		Sat. Nav. (basic test only)	~		
		Reversing camera	~		
Inspected by: Yuki Itohara Date: 17 Oct 2024					

Note: some defects & blemishes may not be displayed in the diagram

I have read and understood this condition guide.

SC = stone chips

10 seater

W = significant scuffs

Service is well overdue.

**Body Inspection Comments** 

Left rear wheel cover is missing.

Delaminated stone crack in C.V.A.

Conditions During Body Inspection:

Name: .....

Signature: .....

Report ID: 19,381,388 Version: 2 Created: 17 Oct 2024

Pass

V

V

V

V

V

V

V

V

V

V

V

~

~

0

0

7

5

Tyres (lowest observed tread depth of tyres)

Brakes

Performance

Hand Brake

Left front

**Right front** 

Left rear

**Right rear** 

Fail

N/A

V

mm

mm

mm

mm