

## **Basic Vehicle Condition Guide**

Report ID: 19,384,604


Version: 2

Created: 10 Jun 2024

Make: Model: Nissan X-Trail **Body Style:** SUV Year: 2020 Registration: MYW594 Reg Expiry: 30 Jul 2024 WoF Expiry: **Odometer:** 21 Jun 2025 119,727 Kms **Good No:** 19384604 VIN: JN1JBAT32A0055408 Next Service: 129,000kms Service History: Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



## **Body Inspection Comments**

Note: some defects & blemishes may not be displayed in the diagram

Two small stone cracks in windscreen, one in right side bottom area of screen & one in left side of screen.

Conditions During Body Inspection: Wet

**Under Carriage & Under Bonnet Inspection Comments** 

<u>Interior Comments</u>		
Seats	Good	
Carpets	Good	
Panels	Good	
Dashboard	Good	

## **General Comments**

Two small holes in fabric back panel on back of right rear seat.

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Jason Young Date: 21 May 2024

Engine Oil level Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission	
Smoke & fumes  Performance  Noise  Cooling System  Coolant condition  Performance  Radiator / Hoses (visual)	
Noise  Cooling System  Coolant condition  Performance  Radiator / Hoses (visual)	
Noise  Cooling System  Coolant condition  Performance  Radiator / Hoses (visual)	
Noise  Cooling System  Coolant condition  Performance  Radiator / Hoses (visual)	
Coolant condition  Performance  Radiator / Hoses (visual)	
Performance   Radiator / Hoses (visual)	
Radiator / Hoses (visual)	
Radiator / Hoses (visual)	
Transmission	
Operation 🗸	
Noise 🗸	
Clutch	~
CV joints 🗸	
Wheel bearings	
Brakes	
Performance 🗸	
Hand Brake	
<b>Tyres</b> (lowest observed tread depth of tyres)	
Left front 4.5 m	nm
Right front 4.5 m	nm
Left rear 7.0 m	nm
Right rear 7.0 m	nm
Spare N/A	
Suspension	
Suspension performance 🗸	
Steering performance 🗸	
Shock absorbers 🗸	
Air Conditioning / Heater	
Operation 🗸	
Electrical / Accessories	
Head lights 🗸	
Tail lights 🗸	
Indicators 🗸	
Dashboard warning lights 🗸	
Tail lights  Indicators  Dashboard warning lights  Wipers (front & rear)  Window winder FL  Window winder FR  Window winder RL  Window winder RR  Rear view mirrors	
Window winder FL	
Window winder FR	
Window winder RL	
Window winder RR	
Radio (basic test only)	
CD (basic test only)	
Number of keys 1	
Central locking	
Central locking  Remote locking	
Central locking	<b>V</b>

I have read and understood this condition guide.

Name: .....

Signature: .....