

Report ID: 21,239,185 Version: 1 09 Jan 2025 Created:

| Make:  | Mitsubishi                                      | Model:               | Outlander              | Body Style:  | Wagon                 |                              | Pass     | Fail    | N/A    |
|--|---|----------------------|------------------------|--|-----------------------|------------------------------|----------|---------|--------|
| Year:  | 2006  | <b>Registration:</b> | GUP23                  | <b>Reg Expiry:</b>                                   | 15 Feb 2025           | Engine                       |          |         |        |
| WoF Expiry:  | 11 Dec 2025                                     | Odometer:            | 184,626 Kms            | Good No:   | 21239185              | Oil level                    | ~        |         |        |
| VIN:   | 7AT0CJ3MX13018706                               | Next Service:        | 176,870km              | Service Histor                                       | <b>y:</b> No          | Smoke & fumes                | ~        |         |        |
|  |   |                      |                        |  |                       | Performance                  | ~        |         |        |
|  | port is not a warranty<br>a guide only. Conside | eration is made      | for age and mileage    | Parts have not                                       | been dismantled or    | Noise                        | ~        |         |        |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. |   |                      |                        |  |                       | Cooling System               |          |         |        |
| a full mechan  | ical inspection prior to                        | purchase and th      | his can be arranged fo | or an additional o                                   | charge.               | Coolant condition            | ~        |         |        |
|  | S SC  |                      | SW SW                  |  | S D                   | Performance                  | ~        |         |        |
| Key:   | 135   | -0                   | 300 300                | -01-   | 30                    | Radiator / Hoses (visual)    | ~        |         |        |
| S = scratch  |   |                      |                        |  |                       | Transmission                 |          |         |        |
| D = dent<br>R = rust   | S SC W  |                      |                        | 715  | SDW                   | Operation                    | ~        |         |        |
| PT = paint defe  |   |                      |                        | $\left( \left  \left( \right) \right\rangle \right)$ |                       | Noise                        | ~        |         |        |
| C = crack  |   |                      |                        | +  | SC                    | Clutch                       |          |         | ~      |
| P = pin dent   | 110   |                      |                        |  | 게                     | CV joints                    | ~        |         | -      |
| * = decals   | sscw 916  |                      |                        | The  | ELL SD                | Wheel bearings               | ~        |         |        |
| SC = stone chips   |   |                      |                        |  |                       | Brakes                       |          |         |        |
| W = significant scuffs S SC S D S D W S D W  |   |                      |                        |  |                       | Performance                  | <b>v</b> |         |        |
|  |   | Note: som            | ne defects & blemishes | may not be disp                                      | blayed in the diagram | Hand Brake                   | ~        |         |        |
| Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram  |   |                      |                        |  |                       | Tyres (lowest observed tread | •        | of tyre | s)     |
| Windscreen stone chips & crack   |   |                      |                        |  |                       |                              |          |         | mm     |
|  |   |                      |                        |  |                       | Right front                  | 4        |         | <br>mm |
|  |   |                      |                        |  |                       | Left rear                    | 4        |         | mm     |
| Canditiana Duvina Dadukana atian   |   |                      |                        |  |                       | Right rear                   |          |         | <br>mm |
| Conditions During Body Inspection: Dry   |   |                      |                        |  |                       | Right rear 5 mm   Spare Yes  |          |         |        |
| Under Carriage & Under Bonnet Inspection Comments  |   |                      |                        |  |                       | Suspension                   |          |         |        |
|  | -   |                      |                        |  |                       | Suspension performance       | ~        |         |        |
| Underbody surface rust<br>Front inner cv boots seeping grease  |   |                      |                        |  |                       | Steering performance         | ~        |         |        |
| Engine oil leak  |   |                      |                        |  |                       | Shock absorbers              | ~        |         |        |
|  |   |                      |                        |  |                       | Air Conditioning / Heater    | V        |         |        |
|  |   |                      |                        |  |                       |                              |          |         |        |
| Interior Comments  |   |                      |                        |  |                       | Operation 🖌                  |          |         |        |
|  |   |                      |                        |  |                       |                              |          |         |        |
| Seats  | Average   |                      |                        |  |                       | -                            | ~        |         |        |
| Carpets  | Average   |                      |                        |  |                       | Tail lights<br>Indicators    | <b>v</b> |         |        |
|  |   |                      |                        |  |                       |                              | ~        |         |        |
| Panels   | Poor  |                      |                        |  |                       | Dashboard warning lights     | ~        |         |        |
| Dashboa  | rd Good   |                      |                        |  |                       | Wipers (front & rear)        | ~        |         |        |
|  |   |                      |                        |  |                       | Window winder FL             | ~        |         |        |
| General (  | Comments  |                      |                        |  |                       | Window winder FR             | ~        |         |        |
|  | <u>commento</u>                                 |                      |                        |  |                       | Window winder RL             | ~        |         |        |
|  |   |                      |                        |  |                       | Window winder RR             | •        |         |        |
|  |   |                      |                        |  |                       | Rear view mirrors            | ~        |         |        |
|  |   |                      |                        |  |                       | Radio (basic test only)      | ~        |         |        |
|  |   |                      |                        |  |                       | CD (basic test only)         | ~        |         |        |
|  |   |                      |                        |  |                       | Number of keys               | 1        |         |        |
| Road Conditions During Test Drive: Dry   |   |                      |                        |  |                       | Central locking              | ~        |         |        |
| Engine Timing Mechanism: Timing Chain  |   |                      |                        |  |                       | Remote locking               | ~        |         |        |
|  |   |                      |                        |  |                       | Sat. Nav. (basic test only)  |          |         | ~      |
| Evidence   | ог сапт вен керіас                              | ement: N             | lot Applicable         | Kms:   |                       | Reversing camera             |          |         | ~      |
| Inspected by: Rowan Fey Date: 09 Jan 2025  |   |                      |                        |  |                       |                              |          |         |        |
|  |   |                      |                        |  |                       |                              |          |         |        |

I have read and understood this condition guide.

Name: .....

Signature: .....