

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or		Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.		Cooling System			
a fuil mechanical inspection prior to purchase and this can be arranged for an additional charge.		Coolant condition	~		
		Performance	~		
Key: S = scratch D = dent R = rust PT = paint defect C = crack P = pin dent * = decals		Radiator / Hoses (visual)	~		
		Transmission			
		Operation	~		
		Noise	~		
		Clutch			~
		CV joints	~		
		Wheel bearings	~		
SC = stone chips	Brakes				
W = significant scuffs		Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram		Hand Brake	~		
		Tyres (lowest observed tread	ed tread depth of tyres)		
		Left front	6.6 mm		
		Right front	6.6	5	mm
		Left rear	4.1	1	mm
Conditions During Body Inspection: Dry		Right rear	4.1	1	mm
Under Carriage & Under Bonnet Inspection Comments		Spare	Yes		
		Suspension			
		Suspension performance	~		
		Steering performance	~		
		Shock absorbers	~		
		Air Conditioning / Heater			
		Operation	~		
Interior Comments		Electrical / Accessories			
Seats Good		Head lights	~		
Good		Tail lights	~		
Carpets Cord		Indicators	~		
Panels Good		Dashboard warning lights	~		
Good	ood	Wipers (front & rear)	~		
Dashboard		Window winder FL	~		
		Window winder FR	~		
General Comments Steering Wheel worn		Window winder RL	~		
		Window winder RR	~		
		Rear view mirrors	~		
		Radio (basic test only)	~		
		CD (basic test only)			~
		Number of keys	2		
Road Conditions During Test Drive: Dry		Central locking	~		
		Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:		Sat. Nav. (basic test only)	~		
		Reversing camera	~		
Inspected by: Lindsay Malpas Date: 01 Nov 2024					

I have read and understood this condition guide.

Name:

 Report ID:
 21,265,425

 Version:
 2

 Created:
 07 Nov 2024

Fail

N/A

Pass

V

V

V