

Report ID: 21,302,064 Version: 4 10 Dec 2024 Created:

Make:	Lexus	Model:	LX	Body Style:	SUV		Pass	Fail	N/A
Year:	2022	Registration:	PMF983	Reg Expiry:	10 Aug 2024	Engine			
WoF Expiry:	11 Aug 2025	Odometer:	108,504 Kms	Good No:	21302064	Oil level	~		
VIN:	JTJPABCX404000993	Next Service:	120,000km	Service Histor	y: No	Smoke & fumes	~		
						Performance	V		
	port is not a warranty		for ago and milaago	Parts have not	been dismonthed or	Noise	V		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	LSC	-01-		Radiator / Hoses (visual)	V		
S = scratch						Transmission			
D = dent R = rust SC D D D D D D D D D D D D D D D D D D						Operation	V		
PT = paint defe				$\left(\left \right\rangle \right)$		Noise	V		
C = crack					SC	Clutch			~
P = pin dent	HIS				74114	CV joints	~		
* = decals	sc 816					Wheel bearings	V		
SC = stone chips						Brakes			I
W = significant scuffs						Performance	V		
Body Incr		Note: som	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	d depth	of tyre	es)
Windscreen cracked Passenger rear taillight cracked									mm
						Right front		5	mm
						Left rear		5	mm
Conditions During Body Inspection: Dry						Right rear	6 mm		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Slight Engine oil seep						Suspension performance	~		
Underbody 4 wheel dri	surface rust					Steering performance	V		
- wheel an						Shock absorbers	V		
						Air Conditioning / Heater	1		1
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
<u></u>	Average					Tail lights	~		
Carpets	//veluge					Indicators	~		
Panels	Good					Dashboard warning lights	V		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	·					Window winder FR	~		
General Comments						Window winder RL	~		
The battery has been replaced but it is still becoming flat after time.						Window winder RR	~		
						Rear view mirrors	V		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
	-					Remote locking	~		
						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Ben Nicholson Date: 10 Dec 2024									

I have read and understood this condition guide.

Name:

Signature: