

Report ID: 21,389,096 3 Version: 12 Dec 2024 Created:

Signature:

Make:	Hyundai	Model:	Tucson	Body Style:	SUV		Pass	Fail	N/A	
Year:	2019	Registration:	QYU714	Reg Expiry:	26 Feb 2025	Engine				
WoF Expiry:	23 May 2025	Odometer:	90,000 Kms	Good No:	21389096	Oil level	~			
VIN:	TMAJ2813MKJ841936	Next Service:	91000	Service Histor	y: Yes	Smoke & fumes	~			
Notes This yes						Performance	~			
	port is not a warranty a guide only. Consid		for age and mileage	. Parts have not	been dismantled or	Noise	V			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
		purchase and t	nis can be analiged ic		inarge.	Coolant condition	~			
		\sim				Performance	~			
Key: S = scratch		$\overline{(0)}$		5(O)-		Radiator / Hoses (visual)	~			
						Transmission				
R = rust	SC PIP			10		Operation	~			
PT = paint defe	ect NP	1				Noise	~			
C = crack					D	Clutch			~	
P = pin dent	sc dl				241 <u>16</u>	CV joints	~			
* = decals SC = stone chi		A O		10	E S	Wheel bearings	~			
W = significant scuffs						Brakes				
, i significant		\mathcal{O}	S S		S D	Performance	~			
Body Insr	pection Comments	Note: son	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~			
body inspection comments						Tyres (lowest observed tread depth of tyres)				
						Left front	5	.0	mm	
						Right front	5	.0	mm	
						Left rear	6	.0	mm	
Conditions During Body Inspection: Dry						Right rear	6.0 mr		mm	
						Spare	Yes			
Under Ca	rriage & Under Boi	nnet Inspectio	on Comments			Suspension				
2Wheel driv	/e.					Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater	•			
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
Correcto						Tail lights	~			
Carpets	Good					Indicators	~			
Panels	Good					Dashboard warning lights	~			
						Wipers (front & rear)	~			
Dashboa	rd Good					Window winder FL	~			
						Window winder FR	~			
General C	<u>Comments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)			~	
						Number of keys	2		_	
Road Conditions During Test Drive: Dry Central locking							~			
	-					Remote locking	~			
-	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
Inspected	Inspected by: Rajesh Mayan Date: 03 Dec 2024									

I have read and understood this condition guide.

Name: