

Report ID: 21,415,052 Version: 1 Created: 08 Jan 2025

Make:	Toyota	Model:	Hiaco	Body Style:	Van		Pass	Fail	N/A
	Toyota		Hiace		Van 27 Eeb 2025	Engine	rass	r'all	IN/A
Year: WoE Expiru:	2008	Registration: Odometer:	EJP955	Reg Expiry: Good No:	27 Feb 2025	Engine			r –
WoF Expiry:			461,407 Kms		21415052	Oil level	~		
VIN:	JTFPT22P900002056	Next Service:	465200kms	Service Histor	y: No	Smoke & fumes	~		
Note: This report is not a warranty						Performance	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
Key:	S S		S P SC S D	S	S SC	Performance	~		
S = scratch						Radiator / Hoses (visual)	~		
						Transmission			
R = rust	- Alb					Operation	~		
PT = paint def	ect N	1				Noise	~		
C = crack						Clutch	~		
P = pin dent	s de				2416	CV joints	~		
* = decals		10		10	ED SP	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant scutts S S S D S D S D S S S D						Performance	~		
Body Incr	pection Comments	Note: son	ne defects & blemishes	s may not be disp	played in the diagram	Hand Brake	~		
	Section comments					Tyres (lowest observed trea	d depth	of tyre	es)
Stone chips in windscreen.						Left front 5.9 mi			mm
Drivers Seat torn All Rear Seats worn and some torn						Right front	6	.1	mm
Air vent selector broken						Left rear	4.6		mm
Conditions During Body Inspection: Dry						Right rear	3.8		mm
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	-					Suspension performance	~		
Engine Oil I	eaks					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	V		
						Operation			
Interior Comments						Electrical / Accessories			~
					Head lights				
Seats	Poor							~	
Carpets	All Rubber	r				Tail lights	~		
						Indicators	~		
Panels	Poor					Dashboard warning lights	~		
Dashboa	rd Poor					Wipers (front & rear)	~		
						Window winder FL	~		
Concret						Window winder FR		~	
<u>General Comments</u>						Window winder RL			~
Condition of Van is a reflection of the Kms travelled.						Window winder RR			~
Front Toyof	ta Badge missing					Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	'es	Kms: 43	32,450	Reversing camera			~
		· · · -							
Inspected by: Lindsay Malpas Date: 30 Dec 2024									
I have read and understood this condition guide. Name:									