

Report ID: 21,415,204 2 Version: 12 Dec 2024 Created:

Make:	Mazda	Model:	Mazda2	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2019	Registration:	MHS508	Reg Expiry:	11 Feb 2025	Engine			
WoF Expiry:	08 Aug 2025	Odometer:	87,286 Kms	Good No:	21415204	Oil level	~		
VIN:	MM0DJ2HAA0W459554	Next Service:	92493kms	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	r an additional c	harge.	Coolant condition	~		
	SC W					Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust SW A A A A A A A A A A A A A A A A A A						Operation	~		
PT = paint defe		r I		$\left[\left(\right) \right]$		Noise	~		
C = crack				$+ \mathbf{\nabla}$		Clutch			~
P = pin dent	HIG				74114	CV joints	~		
* = decals SC 919						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
Deskulas		Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments							Tyres (lowest observed tread depth of tyres)		
Dent in Left Sill.						Left front			
Parcel Tray pivot missing						Right front		.3	 mm
						Left rear		.5	mm
Conditions During Rody Inspection:						Right rear	-		 mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	-					Suspension performance	~		
Front unde	rbody scuffs					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	V		
Interior Comments						Operation 🖌			
Seats	Good						~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	v		
Dashboa	rd Good					Wipers (front & rear) Window winder FL	~		
							~		
General (Comments					Window winder FR	~		
	<u>e</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		┝──┤
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Con	ditions During Tes	t Drive:	Dry			Central locking	~		
Engine Ti	ning Mechanism:	Timing	Chain			Remote locking	~		<u> </u>
						Sat. Nav. (basic test only)			~
Lvidence		ement. N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Lindsay Malpas Date: 04 Dec 2024									

I have read and understood this condition guide.

Name:

Signature: