

Report ID: 21,415,227 Version: 2 03 Dec 2024 Created:

Make:	Holden	Model:	Commodore	Body Style:	Utility		Pass	Fail	N/A
Year:	2017	Registration:	LBG473	Reg Expiry:	30 Nov 2025	Engine			
WoF Expiry:	13 Dec 2025	Odometer:	201,544 Kms	Good No:	21415227	Oil level	~		
VIN:	6G1FA4E37HL322285	Next Service:	209000 kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Noise	~		
						Cooling System			
						Coolant condition	~		
	SC		P SC P SC		S P	Performance	~		
Ney.						Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission	Transmission		
R = rust PT = paint defect						Operation	~		
						Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		
- decais						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant scurs SD PSC S P						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Spare wheel in the back not mounted.						Tyres (lowest observed tread depth of tyres)			
						Left front 5.7			mm
						Right front	6	.0	mm
						Left rear	3	.4	mm
Conditions During Body Inspection: Dry						Right rear	4.6 mm		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	_		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights		~	
Carpote	Poor					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	Poor					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL			~
Left park light out. Left number plate light out. Left high beam out. X Police vehicle so has extra aerial holes in the roof and a panel on the dash. Drivers seat belt frayed. High stop light out.						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	3		
Road Conditions During Test Drive: Dry							~		
Engine Timing Mechanism: Timing Chain							~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms: Reversing camera									~
Evidence	oi Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Chris McQuade Date: 03 Dec 2024									

I have read and understood this condition guide.

Name:

Signature: