

Basic Vehicle Condition Guide

Report ID: 21,415,258


Version: 1

Created: 02 Dec 2024

Make: Model: Mitsubishi Outlander **Body Style:** SUV Year: 2020 Registration: MZQ957 Reg Expiry: 27 Aug 2025 WoF Expiry: **Odometer: Good No:** 23 Sep 2025 91,155 Kms 21415258 VIN: JMFXLGF6WLZ000715 **Next Service:** 106000kms Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Drivers door seal torn. Missing back left head rest.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | | |
|--------------------------|---------|--|--|--|
| Seats | Average | | | |
| Carpets | Average | | | |
| Panels | Good | | | |
| Dashboard | Good | | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: **Lindsay Malpas**

Name:

| Cleate | u. 02 | 2 DCC 2 | .024 |
|------------------------------|-----------------------|---------|------|
| | Pass | Fail | N/A |
| Engine | • | | |
| Oil level | ~ | | |
| Smoke & fumes | v v | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | • | • | • |
| Coolant condition | ~ | | |
| Performance | V | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | • | • | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | 5.0 mm | | mm |
| Right front | 5.5 | | mm |
| Left rear | 3.7 | | mm |
| Right rear | 4.0 | | mm |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | <u> </u> | | |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | ~ | | |
| Window winder FL | V V V V V | | |
| Window winder FR | <i>y</i> | | |
| Window winder RL | • | | |
| Window winder RR | • | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | 1 | | |
| CD (basic test only) | | | ./ |
| Number of keys | 1 | | |
| Central locking | • | | |
| Remote locking | • | | - |
| Sat. Nav. (basic test only) | | | ., |
| | ., | | |
| Reversing camera | | | |

02 Dec 2024

Signature: