

Basic Vehicle Condition Guide

Report ID: 22,197,286


Version: 1

Created: 01 Dec 2023

Make: Model: Nissan Leaf **Body Style:** Hatchback Year: 2015 Registration: MQK129 Reg Expiry: 17 Jun 2024 WoF Expiry: **Odometer: Good No:** 21 Mar 2024 44,512 Kms 22197286 VIN: 7AT0DH8KX19118961 Next Service: Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

FWD

| Interior Comments | | | | | |
|-------------------|-----------|---------|--|--|--|
| | Seats | Good | | | |
| | Carpets | Good | | | |
| | Panels | Average | | | |
| | Dashboard | Good | | | |

| | _ |
|---------|----------|
| General | Comments |

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Unknown

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Todd Cullum Date: 01 Dec 2023

Name:

| | Pass | Fail | N/A | | |
|--|-----------------------|------|-----|--|--|
| Engine | | | | | |
| Oil level | | | ~ | | |
| Smoke & fumes | | | ~ | | |
| Performance | V | | | | |
| Noise | ~ | | | | |
| Cooling System | | | | | |
| Coolant condition | ~ | | | | |
| Performance | \(\times \) | | | | |
| Radiator / Hoses (visual) | ~ | | | | |
| Transmission | | | | | |
| Operation | ~ | | | | |
| Noise | ~ | | | | |
| Clutch | | | ~ | | |
| CV joints | ~ | | | | |
| Wheel bearings | ~ | | | | |
| Brakes | | | | | |
| Performance | ~ | | | | |
| Hand Brake | ~ | | | | |
| Tyres (lowest observed tread depth of tyres) | | | | | |
| Left front | 8 | 3 | mm | | |
| Right front | 8 | 3 | mm | | |
| Left rear | 6 | 5 | mm | | |
| Right rear | 6 | 5 | mm | | |
| Spare | | No | | | |
| Suspension | | | | | |
| Suspension performance | ~ | | | | |
| Steering performance | \ \ \ \ \ \ | | | | |
| Shock absorbers | ~ | | | | |
| Air Conditioning / Heater | | | | | |
| Operation | ~ | | | | |
| Electrical / Accessories | | | | | |
| Head lights | ~ | | | | |
| Tail lights | / | | | | |
| Indicators | ~ | | | | |
| Dashboard warning lights | V V V V V | | | | |
| Wipers (front & rear) | ~ | | | | |
| Window winder FL | <i>\</i> | | | | |
| Window winder FR | <i>'</i> | | | | |
| Window winder RL | <i>'</i> | | | | |
| Window winder RR | <i>'</i> | | | | |
| Rear view mirrors | | | | | |
| Radio (basic test only) | • | | | | |
| CD (basic test only) | V | | | | |
| Number of keys | 1 | | | | |
| Central locking | / | | | | |
| Remote locking | • | | | | |
| Sat. Nav. (basic test only) | V | | | | |
| Reversing camera | ~ | | | | |

Signature: