

Report ID: 365 4 Version:

Created:	12 Dec 2024

Make:	Hyundai	Model:	Elantra	Body Style:	Sedan		Pass	Fail	N/A
Year:	2017	Registration:	KZW606	Reg Expiry:	14 Apr 2025	Engine			L
WoF Expiry:		Odometer:	121,700 Kms	Good No:	22370725	Oil level	~		
VIN:	KMHD741FMJU561447	Next Service:	135000 kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		f	Dauta have used		Noise	~		
diagnostic te	a guide only. Conside sting undertaken. The	vehicle has been	driven up to 50km/h	from cold. The	Vendor recommends	Cooling System	•		<u> </u>
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional c	harge.	Coolant condition		~	
						Performance	~	•	
Key:	SD S	-0				Radiator / Hoses (visual)	~		
S = scratch	Re	A U			X	Transmission	•		
D = dent	SPT 616			The	EID S	Operation	~		
R = rust PT = paint def				\int	JHIH	Noise	~		
C = crack				$+ \mathbf{\nabla}$		Clutch	•		~
P = pin dent					세비	CV joints	~		
* = decals	s 916			The	ELIPS-	Wheel bearings	~		
SC = stone chi	/	20		10L	¥ —	Brakes	•		
W = significan	t scuffs S	$-\emptyset$	P		ПР	Performance	~		
		Note: som	le defects & blemishes	may not be disp	laved in the diagram	Hand Brake	•	~	
Body Insp	pection Comments					Tyres (lowest observed tread	l denth	-	 >s)
Rear bump	er support surface rust					Left front	3.	,	mm
						Right front	3.	-	mm
						Left rear	5.		mm
			-			Right rear	5.		mm
Condition	ns During Body Ins	pection:	Dry			Spare	<u> </u>	Yes	
Under Ca	rriage & Under Bor	net Inspectio	n Comments			Suspension		Tes	
						Suspension performance	~		
FWD						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	V		
Interior C	omments					Electrical / Accessories	~		
						Head lights			
Seats	Good						 		
Carpets	Good					Tail lights Indicators	~		
							~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear) Window winder FL	~		<u> </u>
							v		──
General (Comments					Window winder FR Window winder RL	~		──
							~		<u> </u>
Handbrake W/S stone of	needs to be pulled high hip in CVA	٦.				Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Con	ditions During Tes	t Drive:	Dry			Central locking	~		\mid
Engine Ti	ming Mechanism:	Timing (- hain			Remote locking	~		
-	of Cam Belt Replac		lot Applicable	Kms:		Sat. Nav. (basic test only)			~
				14115.		Reversing camera	~		
Inspecte	Inspected by: Eleoit Kumar Date: 16 Jun 2024								
· · ·	-								

Name:

Signature: