

Under Carria	ne & Under Bonnet	Inspection Comments
onaci cumu	<u>je u onaci bonnet</u>	inspection comments

			Steering performance	~			
			Shock absorbers	~			
				Air Conditioning / Heater			
			Operation	~			
Interior Comments			Electrical / Accessories				
Seats	Good		Head lights	~			
Carpote			Tail lights	~			
Carpets	Good		Indicators	~			
Panels	Good		Dashboard warning lights	~			
			Wipers (front & rear)	~			
Dashboard	Good		Window winder FL	~			
			Window winder FR	~			
General Comments			Window winder RL	~			
			Window winder RR	~			
			Rear view mirrors	~			
			Radio (basic test only)	~			
			CD (basic test only)		V		
			Number of keys	2			
Road Conditions During Test Drive: Dry			Central locking	~			
			Remote locking	~			
Engine Timing Mechanism: Cambelt			Sat. Nav. (basic test only)		V		
Evidence of Cam Belt Replacement: No Kms:			Reversing camera	~			
Inspected by: Hoani Saunders			Date: 23 Dec 20	24			

I have read and understood this condition guide.

Name:

Signature:

N/A

V

mm

mm

mm

mm

V

Suspension

Suspension performance