

Report ID: 22,908,145 Version: 1 23 Dec 2024 Created:

Signature: .....

Make:	KIA	Model:	Seltos	Body Style:	SUV		Pass	Fail	N/A
Year:	2022		PJD147	Reg Expiry:	28 Jun 2025	Engine	I		
WoF Expiry:		Odometer:	33,940 Kms	Good No:	22908145	Oil level	~		
VIN:	KNAEP81ATN735400(	Next Service:	45,000 Kms	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
			SP			Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	SC W			710	HIV SC	Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack					SC	Clutch			~
P = pin dent	sc dP				74116	CV joints	~		
* = decals		10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
w = significan			P			Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
Stone chip in front windscreen						Left front	4.0 mm		mm
						Right front	4.	.5	mm
						Left rear	3.	.0	mm
Conditions During Body Inspection: Dry						Right rear	3.0 n		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	iter		
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	<		
Correcto						Tail lights	<		
Carpets	Good					Indicators	۲		
Panels	Good					Dashboard warning lights	~		
Dashboa						Wipers (front & rear)	~		
	rd Good					Window winder FL	~		
						Window winder FR	۲		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	2		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			2
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanism. That a Chata						Remote locking	2		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected	d by: Hoani Saunders					Date: 23 Dec 20	24		
inspected	u by. Houri Jaunaers						- '		

I have read and understood this condition guide.

Name: .....