

Basic Vehicle Condition Guide

Report ID: 22,908,682


Version: 4

Created: 12 Dec 2024

Make: Model: Toyota Hilux **Body Style:** Utility Year: 2016 Registration: JNN489 Reg Expiry: 14 Jan 2025 **Odometer:** WoF Expiry: **Good No:** 10 Feb 2025 277,148 Kms 22908682 VIN: MR0JA3DD800340224 Next Service: 288,000 Kms Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Large stone chips in front windscreen

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Stains. Large rip on drivers seat otherwise good		
Carpets	Wear on drivers side foot rest otherwise good		
Panels	Good		
Dashboard	Good		

General Comments

Radio steering wheel control doesn't work due to an aftermarket head unit

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Hoani Saunders

Pass	Fail	N/A		
	•			
~				
~				
~				
~				
~				
~				
~				
Transmission				
~				
~				
~				
		~		
~				
		1		
~				
~				
Hand Brake Tyres (lowest observed tread depth of tyres)				
		mm		
Spare Yes Suspension				
V				
1				
<i>y</i>				
./				
.,				
1				
<u> </u>				
-				
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \				
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \				
 				
V				
		i .		
~				
		~		
		~		
~		<i>v</i>		
1		<i>v</i>		
1		<i>v</i>		
	ママママママママママママママママママママママママママママママママママママ	V		

I have read and understood this condition guide.

Name:

Signature: