

Report ID: 22,908,973 4 Version: 12 Dec 2024 Created:

Make:	Toyota	Model:	Hilux	Body Style:	Utility		Pass	Fail	N/A	
Year:	2018	Registration:	LSL872	Reg Expiry:	28 Oct 2025	Engine			<u> </u>	
WoF Expiry:		Odometer:	192,672 Kms	Good No:	22908973	Oil level	~			
VIN:	MR0JA3DD40034469	Next Service:	-	Service Histor		Smoke & fumes	~			
					,	Performance	~			
	port is not a warranty		<i>с</i> , , , , , , , , , , , , , , , , , , ,	-		Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition				
						Performance	~			
Key:	S	-0	IS IS		S	Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent						Operation	~			
R = rust				10	JHIK	Noise	~			
PT = paint def C = crack				+		Clutch			~	
P = pin dent	Ho					CV joints			~	
* = decals	SSC PR			AL-		Wheel bearings				
SC = stone chips						Brakes	~			
W = significant scuffs S S S D S P S S						Performance	~		1	
		Note: son	ne defects & blemishes	may not be disr		Hand Brake	~			
Body Inst	pection Comments	1016.301	le delects & blemsnes	s may not be disp	layed in the diagram		•	ofture		
Front bumper cracked on right side						Tyres (lowest observed tread depth of tyres)				
Front lower grill needs refitting						Left front	5.		mm	
						Right front	5.		mm	
						Left rear	5.		mm	
Conditions During Body Inspection: Wet						Right rear	5.6 mm		mm	
Under Carriage & Under Bonnet Inspection Comments						Spare				
		meemspeede	<u>on comments</u>			Suspension				
						Suspension performance	~		<u> </u>	
						Steering performance	~		<u> </u>	
						Shock absorbers	~			
						Air Conditioning / Heater				
Interior Comments						Operation 🖌				
					Electrical / Accessories					
Seats	Good					Head lights	~		<u> </u>	
Carpets	Good					Tail lights	~			
						Indicators	~		──	
Panels	centre cor	nsole has screw h	oles otherwise good			Dashboard warning lights	~		<u> </u>	
Dashboa	rd Good					Wipers (front & rear)	~			
						Window winder FL	~			
General	<u>Comments</u>					Window winder FR	~		<u> </u>	
						Window winder RL	~		<u> </u>	
						Window winder RR	~		<u> </u>	
						Rear view mirrors	~		<u> </u>	
						Radio (basic test only)	~		<u> </u>	
						CD (basic test only)	~			
L						Number of keys	1			
Road Con	ditions During Tes	t Drive:	Wet			Central locking	~		<u> </u>	
Engine Ti	ming Mechanism:	Timing (Chain			Remote locking	~		<u> </u>	
-	-			Kmc		Sat. Nav. (basic test only)			~	
	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
Inspecte	Inspected by: Kyle Kelly Date: 01 Dec 2024									

I have read and understood this condition guide.

Name:

Signature: