

Report ID: 22,909,251 Version: 1 25 Nov 2024 Created:

| Make: | Toyota | Model: | Hilux | Body Style: | Utility | | Pass | Fail | N/A |
|--|---------------------------|--------------------|------------------------|-------------------|----------------------|--|---|------|-----|
| Year: | 2018 | Registration: | LSL875 | Reg Expiry: | 30 Oct 2025 | Engine | | | |
| WoF Expiry: | 31 Oct 2025 | Odometer: | 147,198 Kms | Good No: | 22909251 | Oil level | ~ | | |
| VIN: | MR0JA3DD900344699 | Next Service: | 150,000 Kms | Service Histor | y: Yes | Smoke & fumes | ~ | | |
| | | | · | | | Performance | ~ | | |
| | port is not a warranty | | с I II | | | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| | | | | | | Coolant condition | | | |
| | | | | | | Performance | ~ | | |
| Key: | SC | -0 | LP | | s | Radiator / Hoses (visual) | ~ | | |
| S = scratch | STE | A CO | | | X | Transmission | • | | |
| D = dent | scw 6/6 | | | The | S PT P W | Operation | ~ | | |
| R = rust | | | | 10 | JHIH | Noise | ~ | | |
| PT = paint defe C = crack | ect III | | | + | SC | Clutch | ~ | | ~ |
| P = pin dent | Ho | | | | JUII —— | CV joints | | | ~ |
| * = decals | sc pp | | | AL- | SDRPW | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | | Brakes | | |
| W = significant scuffs | | | | | | | | | 1 |
| | | Notorer | ne defects & blemishes | | | Performance Hand Brake | <td></td><td></td> | | |
| | pection Comments | Note: son | le délects à Diemisnes | s may not be disp | nayed in the diagram | | | | |
| Small dent on right side lower sill Tape on inside of drivers door jamb | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| rape on ins | ide of drivers door jamic |) | | | | Left front | 7. | | mm |
| | | | | | | Right front | 6. | | mm |
| | | | | | | Left rear | 6. | | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 6.7 mm | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Spare | Yes | | |
| | mage & onder bor | inet inspectic | <u>In comments</u> | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| Interior Comments | | | | | | Operation 🖌 | | | |
| Slight wear on drivers seat | | | | | | Electrical / Accessories | | | |
| Seats | Signt wea | i oli ulivels seat | | | | Head lights | ~ | | |
| Carpets | Good | | | | | Tail lights | ~ | | |
| | Course had | | -1- | | | Indicators | ~ | | |
| Panels | Screw note | es in centre cons | UIC | | | Dashboard warning lights | ~ | | |
| Dashboa | rd Good | | | | | Wipers (front & rear) | ~ | | |
| | | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| General C | <u>Comments</u> | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 1 | | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | |
| | | · | | | | Remote locking | ~ | | |
| - | ming Mechanism: | Timing | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | ~ | | |
| Inspected by: Hoani Saunders Date: 25 Nov 2024 | | | | | | | | | |

Name:

Signature: