

Report ID: 22,935,722 1 Version: 13 Jan 2025 Created:

| Make: | Mazda | Model: | CX-5 | Body Style: | SUV | | Pass | Fail | N/A | |
|--|------------------------|----------------------|---------------------|---------------------|--------------------------|--|----------|------|----------|--|
| Year: | 2016 | Registration: | KEF587 | Reg Expiry: | 03 Nov 2025 | Engine | <u> </u> | | 1 | |
| WoF Expiry: | 31 Oct 2025 | Odometer: | 190,853 Kms | Good No: | 22935722 | Oil level | ~ | | | |
| VIN: | JM0KE103200388004 | Next Service: | 193600 | Service Histor | y: Yes | Smoke & fumes | ~ | | | |
| | | | | | | Performance | ~ | | | |
| | port is not a warranty | | 6 | | | Noise | ~ | | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | | |
| | | | | | | Coolant condition | | | | |
| | | | | | | Performance | ~ | | | |
| Key: | SC | -0 | SC S | 201 | S | Radiator / Hoses (visual) | ~ | | | |
| S = scratch | Re | A U | | | X. | Transmission | • | | L | |
| D = dent | sc 6/6 | | | | EID S | Operation | ~ | | | |
| R = rust PT = paint def | | | | | THA | Noise | ~ | | | |
| C = crack | | | - | + | SC | Clutch | • | | ~ | |
| P = pin dent | Ho | | | | | CV joints | ~ | | | |
| * = decals | sc 916 | | | The | ETP SD | Wheel bearings | ~ | | | |
| SC = stone chips | | | | | | Brakes | 3 | | | |
| W = significan | t scuffs SC | - | SC D SC | | SC | Performance | ~ | | | |
| | | Note: som | e defects & blemish | les may not be disp | laved in the diagram | Hand Brake | ~ | | <u> </u> | |
| Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram | | | | | | | • | | | |
| Windscreen pitted/chips | | | | | | Tyres (lowest observed tread depth of tyres) Left front 4.0 mm | | | | |
| | | | | | | | | | mm | |
| | | | | | | Right front | 4. | - | mm | |
| | | | | | | Left rear | 5. | | mm | |
| Conditions During Body Inspection: | | | | | | Right rear | 5.0 mm | | mm | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Spare | Yes | | | |
| | | meemspeede | <u>Comments</u> | | | Suspension | | | | |
| | | | | | | Suspension performance | ~ | | <u> </u> | |
| | | | | | | Steering performance | ~ | | <u> </u> | |
| | | | | | | Shock absorbers | ~ | | | |
| | | | | | | Air Conditioning / Heater | | | T | |
| Interior Comments | | | | | | Operation 🖌 | | | | |
| | | | | | Electrical / Accessories | | | | | |
| Seats | Average | | | | | Head lights | ~ | | <u> </u> | |
| Carpets | Average | | | | | Tail lights | ~ | | <u> </u> | |
| | | | | | | Indicators | ~ | | <u> </u> | |
| Panels | Average | | | | | Dashboard warning lights | ~ | | <u> </u> | |
| Dashboa | rd Average | | | | | Wipers (front & rear) | ~ | | <u> </u> | |
| | Avelage | | | | | Window winder FL | ~ | | <u> </u> | |
| Concret | Commonte | | | | | Window winder FR | ~ | | <u> </u> | |
| General | <u>Comments</u> | | | | | Window winder RL | ~ | | <u> </u> | |
| | | | | | | Window winder RR | ~ | | <u> </u> | |
| | | | | | | Rear view mirrors | ~ | | <u> </u> | |
| | | | | | | Radio (basic test only) | ~ | | <u> </u> | |
| | | | | | | CD (basic test only) | ~ | | | |
| | | | | | | Number of keys | 2 | | | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | | |
| с <u> </u> | | | <u></u> | | | Remote locking | ~ | | | |
| - | ming Mechanism: | Timing (| | | | Sat. Nav. (basic test only) | | | ~ | |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | ~ | | | |
| | d by: Jeremy Hutchin | | | | | Date: 13 Jan 202 | 25 | | | |
| Inspecte | | .92 | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: