

Report ID: 22,937,046 Version: 2 26 Nov 2024 Created:

Make:	Holden	Model:	Commodore	Body Style:	Wagon		Pass	Fail	N/A
Year:	2018	Registration:	LLP411	Reg Expiry:	01 Jul 2025	Engine		-	<u> </u>
WoF Expiry:	14 Nov 2025	Odometer:	228,957 Kms	Good No:	22937046	Oil level	~		
VIN:	W0VZM8EC6J110177(	Next Service:	,	Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		<b>,</b> , , , ,			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechan	ical inspection prior to	purchase and the	nis can be arranged	for an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch	STE	A CO	$\overline{\frown}$	100	X	Transmission	•		
D = dent	ISC 6/6				EID S	Operation	~		
R = rust					JHIL	Noise	~		
PT = paint defe C = crack			-	+	D	Clutch			~
P = pin dent	Ho				JIII —	CV joints	~		
* = decals	DSC PR					Wheel bearings	-		<u> </u>
SC = stone chips						Brakes	~		
W = significant scuffs						Performance			
		Noto: com				Hand Brake	~ ~		<u> </u>
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							•	- <b>f t</b> wa	
Holes in Hood lining, RT Holes in Dash Pad & centre console, Aerial plugs in roof, Holes in Front & Rear						Tyres (lowest observed tread depth of tyres)			
Bumpers, R/R Taillight condensation, No spare wheel or tools or jack in Boot, R/F window switch broken, Key remote buttons missing.						Left front	7.		mm
						Right front	7.		mm
						Left rear	8.0		mm
Conditions During Body Inspection: Dry						Right rear	8.	8.0 mm	
Under Carriage & Under Bonnet Inspection Comments						Spare No			
	mage & Onder BOI	mermspectic	<u>on comments</u>			Suspension			·
						Suspension performance	~		<u> </u>
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Average						Electrical / Accessories			
Seats	Avelage					Head lights	~		<u> </u>
Carpets	Average					Tail lights	~		<u> </u>
	A					Indicators	~		<u> </u>
Panels	Average					Dashboard warning lights	~		<u> </u>
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
	•					Window winder FR	~		
<u>General Comments</u>					Window winder RL	~			
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry Central locki						Central locking	~		
		<u> </u>	•			Remote locking	~		
-	ming Mechanism:	Timing (				Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected	d by: Chris Buckley					Date: 06 Nov 20	24		

I have read and understood this condition guide.

Name: .....

Signature: .....