

## **Basic Vehicle Condition Guide**

Report ID: 22,980,869

Version: 2

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

**Transmission** 

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

**Hand Brake** 

Left front

Left rear

Right rear

Suspension

Operation

Head lights
Tail lights
Indicators

Shock absorbers

Air Conditioning / Heater

**Electrical / Accessories** 

Dashboard warning lights

Wipers (front & rear)

Window winder FL
Window winder FR

Window winder RL

Window winder RR

Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Suspension performance
Steering performance

Spare

Right front

Coolant condition
Performance

Radiator / Hoses (visual)

Created: 29 May 2024

Pass

1

~

/

V

1

Tyres (lowest observed tread depth of tyres)

Fail

N/A

1

mm

mm

mm

 $\mathsf{mm}$ 

1

1

6.0

6.2

6.8

6.9

1

/

/

/

1


1

Yes

Make: Model: Ford Transit **Body Style:** Van Year: 2019 Registration: MCU119 **Reg Expiry:** 30 Jun 2024 WoF Expiry: **Odometer:** 24 Jun 2024 144,090 Kms **Good No:** 22980869 VIN: WF03XXTTG3KS10201 Next Service: 133,000 **Service History:** Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



## **Body Inspection Comments**

Note: some defects & blemishes may not be displayed in the diagram

Stone chips in the windscreen, dent and scratch along the left side cant rail,

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Oil around oil cap,

Interior Comments		
Seats	wear and tear and stains	
Carpets	Good	
Panels	wear and tear	
Dashboard	Good	

## General Comments

Inspected by:

Tyre pressure light is on, air con is cold but not freezing,

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Jesse Roberts

I have read and understood this condition guide.

Evidence of Cam Belt Replacement: No

Kms:	Sat. Nav. (basic test only)  Reversing camera	v
Name:	Date: 28 May 20	J24