

Report ID: 22,987,656 Version: 1 10 Jan 2025 Created:

Make:	Nissan	Model:	Leaf	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2014	Registration:	JTQ57	Reg Expiry:	17 Nov 2025	Engine	•			
WoF Expiry:	19 Nov 2025	Odometer:	26,123 Kms	Good No:	22987656	Oil level			~	
VIN:	7AT0DH8KX16101412	Next Service:	36,102kms	Service Histor	y: No	Smoke & fumes			~	
						Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise			~	
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	lical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	~			
	S* S		* W * SC W		SC	Performance	~			
Key:	is (is	-0				Radiator / Hoses (visual)	~			
S = scratch D = dent						Transmission				
D = dent R = rust	*SC			715	BIL SC	Operation	~			
PT = paint defe	ect NP	FI		$\left(\left \left(\right) \right\rangle \right)$		Noise	~			
C = crack						Clutch			~	
P = pin dent	HIC				ᅰ	CV joints	~			
* = decals	* sc gig			-NG	AD w	Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs * W S * SC W P * W W						Performance	~			
Dodulac		Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
Body Inspection Comments						Tyres (lowest observed tread	s (lowest observed tread depth of tyres)			
Fine overspray over vehicle.									mm	
Tyre repair	kit as opposed to spare	wheel, tyre pum	p missing.			Right front		5	mm	
						Left rear			mm	
Condition	as During Padulas	naction	D.			Right rear			 mm	
Conditions During Body Inspection: Dry						Spare N/A				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
	-					Suspension performance	~			
						Steering performance	~		<u> </u>	
						Shock absorbers	~		<u> </u>	
						Air Conditioning / Heater	•			
						Operation	~			
Interior Comments						Electrical / Accessories				
						Head lights	~			
Jeals	Average					Tail lights	~			
Carpets	Average						<i>v</i> <i>v</i>			
Develo						Dashboard warning lights	<i>v</i> <i>v</i>			
Panels	Cargo tray	supplied not for	r this car.			Wipers (front & rear)	<i>v</i> <i>v</i>			
Dashboa	rd Good					Window winder FL				
						Window winder FL Window winder FR	v			
General (Comments						V			
						Window winder RL Window winder RR	v			
Low km, Fu	ll electric Leaf hatch.						~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1			
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		<u> </u>	
Engine Tir	ming Mechanism:	Unknow	/n			Remote locking	~		<u> </u>	
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~	
Lvidence	or carri bert nepide			11113.		Reversing camera	~			
Inspected by: Daryll Timms Date: 10 Jan 2025										
L	· ·									

I have read and understood this condition guide.

Name:

Signature: