

Report ID: 22,987,706 Version: 1 09 Jan 2025 Created:

Make:	Toyota	Model:	Hilux	Body Style:	Utility	7		Pass	Fail	N/A	
Year:	2013	<b>Registration:</b>	HDM427	<b>Reg Expiry:</b>	12 Nov 2025	Er	ngine				
WoF Expiry:	13 Oct 2025	Odometer:	333,990 Kms	Good No:	22987706		Oil level	~			
VIN:	MR0EZ12G704013673	Next Service:	340,000kms	Service Histor	<b>y:</b> Yes		Smoke & fumes	~			
						56	Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or							Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends							Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Coolant condition	~			
						┑┠┐	Performance	~			
Key: SC C SC SC SC PSC							Radiator / Hoses (visual)	~			
S = scratch						Tr	ansmission			I	
D = dent R = rust SSC SD SD							Operation	~			
PT = paint defect							Noise	~			
C = crack							Clutch	~			
P = pin dent							CV joints	-		~	
* = decals SC 919 SP							Wheel bearings	~			
SC = stone chips							Brakes				
W = significant scuffs SC SC C S SC							Performance	~			
		Note: son	ne defects & blemishes	may not be disp	layed in the diagram		Hand Brake	~			
Body Inspection Comments						Т	Tyres (lowest observed tread depth of tyres)				
Grille scratched.						I	Left front 5 mm				
Drivers door seal damaged.							Right front	5		mm	
							Left rear	6		mm	
Conditions During Pody Inspection							Right rear	6		mm	
Conditions During Body Inspection: Dry							Spare Yes				
Under Carriage & Under Bonnet Inspection Comments							Suspension				
							Suspension performance	~			
							Steering performance	~			
							Shock absorbers	~			
							r Conditioning / Heater	·			
							Operation				
Interior Comments							Electrical / Accessories				
Seats Average							Head lights				
	Avelage						Tail lights	~			
Carpets	Average						Indicators	~			
Panels	1						Dashboard warning lights	~			
Faileis		sor mirror cracke	·d.				Wipers (front & rear)	~			
Dashboa	rd Average						Window winder FL	~		$\left  - \right $	
							Window winder FR	~		$\left  - \right $	
General Comments							Window winder RL	~			
2WD manual diesel d/cab ute.							Window winder RR	~			
200 manu	al diesel d/cab die.						Rear view mirrors	~			
							Radio (basic test only)	~			
							CD (basic test only)	~			
							Number of keys	2		L	
Pood Conditions During Test Driver						_  _	Central locking	2			
Road Conditions During Test Drive: Dry							Remote locking	v v			
Engine Timing Mechanism: Cambelt							Sat. Nav. (basic test only)	•		~	
Evidence of Cam Belt Replacement: Yes Kms: 251,700							Reversing camera			~	
										_ <b>*</b>	
Inspected by: Daryll Timms Date: 09 Jan 2025											

Name: .....

Signature: .....