

Report ID: 22,988,319 2 Version: 07 Jan 2025 Created:

Make:	Skoda	Model:	Octavia	Body Style:	Wagon		Pass	Fail	N/A
Year:	2019	Registration:	MHR248	Reg Expiry:	10 Mar 2025	Engine		1	·
WoF Expiry:	05 Dec 2025	Odometer:	105,968 Kms	Good No:	22988319	Oil level	~		
VIN:	TMBKC7NE7K021693	Next Service:	108,000kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:	SC S	-0	P SC P	-01-	PT	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	SC DIE			TIS	SC	Operation	~		
R = rust PT = paint defe				\int	JHH	Noise	~		
C = crack				+	SC	Clutch			~
P = pin dent	Ho					CV joints	~		
* = decals	sc PIK			AL	ELLAR SC	Wheel bearings	~		<u> </u>
SC = stone chips						Brakes	V		
W = significant scuffs P SC P PT P						Performance	~		
		Note: con				Hand Brake	~		<u> </u>
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							•	ofture	
Poor paint repair on rear quarter panels.						Tyres (lowest observed tread depth of tyres)			
Hatch door badge missing.						Left front		.0	mm
						Right front		.0	mm
						Left rear		.0	mm
Conditions During Body Inspection: Wet						Right rear	6.0 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage & onder bor	metinspectic	<u>on comments</u>			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpote	A					Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
Petrol auto Octavia wagon.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		L
Road Conditions During Test Drive: Wet						Central locking	~		\square
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)	~		
Evidence of Cam Belt Replacement: No Kms:						Reversing camera	~		$\left - \right $
L						-	-		<u> </u>
Inspected	Inspected by: Daryll Timms Date: 31 Dec 2024								

I have read and understood this condition guide.

Name:

Signature: