

Basic Vehicle Condition Guide

Report ID: 22,989,028


Version: 2

Created: 19 Dec 2024

Make: Model: Polestar Polestar 2 **Body Style:** Hatchback Year: 2023 Registration: PTR997 Reg Expiry: 15 Mar 2025 **WoF Expiry: Odometer: Good No:** 16 Mar 2026 17,060 Kms 22989028 VIN: YSMVSEFA0PL143332 Next Service: Unknown Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | | |
|--------------------------|------|--|--|--|
| Seats | Good | | | |
| Carpets | Good | | | |
| Panels | Good | | | |
| Dashboard | Good | | | |

General Comments

Tyre repair kit as opposed to spare wheel.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Unknown

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Troy Smith Date: 19 Dec 2024

| | Pass | Fail | N/A | |
|------------------------------|---------------------------------------|---------|-----|--|
| Engine | | | | |
| Oil level | | | ~ | |
| Smoke & fumes | | | ~ | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | \(\sigma \) | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed treac | depth | of tyre | es) | |
| Left front | 4 | 4 | mm | |
| Right front | 4.5 | | mm | |
| Left rear | 5.5 | | mm | |
| Right rear | 5.5 | | mm | |
| Spare | | N/A | | |
| Suspension | | 1 | | |
| Suspension performance | ~ | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation | ~ | | | |
| Electrical / Accessories | | I | | |
| Head lights | - | | | |
| Tail lights | ~ | | | |
| Indicators | <i>'</i> | | | |
| Dashboard warning lights | • | | | |
| Wipers (front & rear) | • | | | |
| Window winder FL | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | | |
| Window winder FR | | | | |
| Window winder RL | ンン | | | |
| Window winder RR | | | | |
| Rear view mirrors | V | | | |
| Radio (basic test only) | - | | ., | |
| CD (basic test only) | 1 | | | |
| Number of keys | 1 | | | |
| Central locking | • | | | |
| Remote locking | V | | | |
| Sat. Nav. (basic test only) | <i>v</i> | | | |
| Reversing camera | | | | |

I have read and understood this condition guide.

Name:

Signature: