

Basic Vehicle Condition Guide

Report ID: 22,989,921


Version: 2

Created: 14 Oct 2024

Make: Model: Hyundai lload **Body Style:** Van Year: 2019 Registration: MFC814 Reg Expiry: 20 Dec 2024 WoF Expiry: **Odometer:** 15 Jul 2025 168,355 Kms **Good No:** 22989921 VIN: KMFWBX7KMLU08964 Next Service: 174,000 kms Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chips in windscreen Spider rust on roof

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Oil leaks from engine and transmission

<u>Interior Comments</u>			
Seats	RF seat base torn		
Carpets	Good		
Panels	LF door trim gouged. Cargo area scuffed		
Dashboard	Scratches centre console		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Dean Sinclair Date: 11 Oct 2024

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	\(\times \)		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	•		•
Operation	~		
Noise	~		
Clutch			~
CV joints			~
Wheel bearings	~		
Brakes	l		
Performance	'		
Hand Brake	~		
Tyres (lowest observed tread	l depth	of tyre	 es)
Left front	5	.0	mm
Right front	6.0		mm
Left rear	5.5		mm
Right rear	5.5		mm
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	✓ ✓		
Shock absorbers	~		
Air Conditioning / Heater			<u> </u>
Operation	V		
Electrical / Accessories			
Head lights	V		
Tail lights	<i>y</i>		
Indicators	V		
Dashboard warning lights	·		
Wipers (front & rear)	V		
Window winder FL	~		
Window winder FR	~		
Window winder RL			.,
Window winder RR			1
Rear view mirrors			
Radio (basic test only)			.,
CD (basic test only)			•
Number of keys	2		
Central locking	•		
Remote locking			<u> </u>
Sat. Nav. (basic test only)			'
Reversing camera	'		

Signature: