

## **Basic Vehicle Condition Guide**

Report ID: 23,016,792


Version:

Created: 05 Aug 2024

Make: **BMW** Model: 1161 **Body Style:** Hatchback Year: 2012 Registration: PZQ141 Reg Expiry: 14 Dec 2024 WoF Expiry: **Odometer:** 13 Jun 2024 75,273 Kms **Good No:** 23016792 VIN: WBA1A12060E947595 **Next Service:** 82900 Service History:

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



## **Body Inspection Comments**

Vehicle has a puncture repair kit No tools or jack

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Rear wheel drive

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

## **General Comments**

Horn does not work Moisture in left side headlight

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: **Timing Chain** 

**Evidence of Cam Belt Replacement:** Not Applicable Kms:

Jaykib Collins Inspected by: Date: 05 Aug 2024

Name: .....

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	\( \times \)		
Noise	~		
Cooling System			1
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			ı
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	 es)
Left front			mm
Right front	7		mm
Left rear	7		mm
Right rear	6		mm
Spare		No	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights		V	
Tail lights	~		
Indicators	-		
Dashboard warning lights	<i>v</i>		
Wipers (front & rear)	\( \triangle \tr		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	<b>v</b>		
Rear view mirrors	~		
Radio (basic test only)			
CD (basic test only)	\( \triangle \)		
Number of keys			
	1		
Central locking	-		
Pamata lacking		1	
Remote locking	·		
Sat. Nav. (basic test only)  Reversing camera			~

Signature: .....