

Report ID: 23,020,200 Version: 1 13 Jan 2025 Created:

Make:	Mitsubishi	Model:	Outlander	Body Style:	SUV		Pass	Fail	N/A	
Year:	2011	<b>Registration:</b>	QZQ231	<b>Reg Expiry:</b>	22 Jul 2025	Engine				
WoF Expiry:	17 Sep 2025	Odometer:	193,856 Kms	Good No:	23020200	Oil level	~			
VIN:	JMFXTCW5WCU000330	Next Service:	7/12/24 or 195277km	Service Histor	<b>y:</b> No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty		for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	lical inspection prior to	purchase and th	his can be arranged f	or an additional o	charge.	Coolant condition	~			
	S SC S		SP SP		S P	Performance	~			
Key:	Lase La	-0	SP SP	-01-	54	Radiator / Hoses (visual)	~			
S = scratch						Transmission	Transmission			
D = dent R = rust						Operation	~			
PT = paint defe				$\left[ \left( \right) \right]$		Noise	V			
C = crack				$+ \mathbb{N}$		Clutch			~	
P = pin dent	HIG				7414	CV joints	~			
* = decals P SC P P						Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs SD S SP S SP S SP						Performance	~			
		Note: som	ne defects & blemishe	s may not be disp	blayed in the diagram	Hand Brake	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							s (lowest observed tread depth of tyres)			
Stone chips in windscreen.									mm	
						Right front		3	 mm	
						Left rear		5	mm	
Conditions Duving Rody Insportion.						Right rear			 mm	
Conditions During Body Inspection: Dry						Spare	5 mm Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
	-					Suspension performance	~			
Surface cor	rosion under bonnet ar	nd front bumper.				Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater	V			
						Operation	~			
Interior Comments						Electrical / Accessories				
						Head lights				
Seals	Good					Tail lights	-			
Carpets	Good						レ レ			
						Dashboard warning lights	-			
Panels	Good					Wipers (front & rear)	レ レ			
Dashboa	rd Good					Window winder FL				
						Window winder FL	<b>v</b>			
General (	Comments					Window winder FR Window winder RL	<b>v</b>			
						Window winder RL Window winder RR	レ レ			
Vehicle dro	ve well.						-			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Dry						Central locking	~			
Engine Tir	ming Mechanism:	Timina	Chain			Remote locking	~			
						Sat. Nav. (basic test only)			~	
	or cam beit neplat	.cmcnt. N	lot Applicable	11115.		Reversing camera			~	
Inspected	d by: Aaron Johnson					Date: 13 Jan 202	25			
	,									

I have read and understood this condition guide.

Name: .....

Signature: .....