

Basic Vehicle Condition Guide

Report ID: 23,020,829


Version: 3

Created: 13 Dec 2024

Make: Model: Hyundai Tucson **Body Style:** SUV Year: 2020 Registration: MUP545 Reg Expiry: 30 Apr 2025 WoF Expiry: **Odometer:** 224,590 Kms **Good No:** 23020829 VIN: TMAJ281ASLJ100459 Next Service: 9/10/25 or 232000km Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Stone chips.

Windscreen has multiple cracks middle top of windscreen.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Inner wear on front tyres.

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Vehicle drove well.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Aaron Johnson Date: 13 Dec 2024

		_	_		
	Pass	Fail	N/A		
Engine					
Oil level	VVV				
Smoke & fumes	~				
Performance	~				
Noise	~				
Cooling System					
Coolant condition	~				
Performance	<i>y y</i>				
Radiator / Hoses (visual)	~				
Transmission					
Operation	'				
Noise	>				
Clutch			~		
CV joints	~				
Wheel bearings	~				
Brakes					
Performance	~				
Hand Brake	>				
Tyres (lowest observed tread	l depth	of tyre	es)		
Left front		3	mm		
Right front		3	mm		
Left rear	-	7	mm		
Right rear	-	7	mm		
Spare		Yes			
Suspension					
Suspension performance	~				
Steering performance	✓ ✓				
Shock absorbers	~				
Air Conditioning / Heater					
Operation	~				
Electrical / Accessories					
Head lights	/				
Tail lights					
Indicators	~				
Dashboard warning lights	~				
Wipers (front & rear)	> > > > > > > > > > > > > > > > > > >				
Window winder FL	~				
Window winder FR	VVV				
Window winder RL	·				
Window winder RR	~				
Rear view mirrors	~				
Radio (basic test only)	~				
CD (basic test only)			~		
Number of keys	2				
Central locking	~				
Remote locking	~				
Sat. Nav. (basic test only)	-		1		
Reversing camera	~				
g camera	_				

I have read and understood this condition guide.

Name:

Signature: