

Basic Vehicle Condition Guide

Report ID: 23,021,301


Version:

12 Dec 2024 Created:

Make: Model: Mercedes-Benz **B-Class Body Style:** Hatchback Year: 2013 Registration: HEL56 Reg Expiry: 01 Jan 2025 **Odometer:** WoF Expiry: **Good No:** 15 Nov 2025 90,148 Kms 23021301 VIN: **Next Service:** WDD2462442J144784 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chips in windscreen.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | | |
|--------------------------|------|--|--|--|
| Seats | Good | | | |
| Carpets | Good | | | |
| Panels | Good | | | |
| Dashboard | Good | | | |

General Comments

Vehicle drove well.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

04 Dec 2024 Aaron Johnson Inspected by: Date:

Name:

| | Pass | Fail | N/A | |
|--|---------------|------|-----|--|
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | <i>V V</i> | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | ~ | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | V | | | |
| Noise | ' | | | |
| Clutch | | | ~ | |
| CV joints | > | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | > | | | |
| Tyres (lowest observed tread depth of tyres) | | | | |
| Left front | 9.0 | | mm | |
| Right front | 9.0 | | mm | |
| Left rear | 6.0 | | mm | |
| Right rear | 6.0 | | mm | |
| Spare | | No | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | <i>V</i> | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation | ~ | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | ~ | | | |
| Dashboard warning lights | ~ | | | |
| Wipers (front & rear) | ~ | | | |
| Window winder FL | V V V V V V V | | | |
| Window winder FR | ~ | | | |
| Window winder RL | ~ | | | |
| Window winder RR | ~ | | | |
| Rear view mirrors | | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | ~ | | | |
| Number of keys | 2 | | | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | | | ~ | |
| Reversing camera | | | | |

Signature: