

Basic Vehicle Condition Guide

Report ID: 23,021,514

Pass

~

~

/

V

1

Tyres (lowest observed tread depth of tyres)

Version: 3

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Right front

Left rear

Right rear

Suspension

Shock absorbers Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL

Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of kevs

Operation

Head lights Tail lights Indicators

Suspension performance Steering performance

Spare

Coolant condition Performance

Radiator / Hoses (visual)

Created: 27 Nov 2024

Fail

N/A

1

mm

mm

mm

 mm

7

7

1

/

/

/

1

1


2

Yes

Make: Model: Holden Cruze **Body Style:** Sedan Year: 2014 Registration: HKJ356 **Reg Expiry:** 29 Oct 2024 WoF Expiry: **Odometer:** 05 Oct 2025 94,094 Kms **Good No:** 23021514 VIN: 6G1PD5EM6EL944527 **Next Service:** 19/05/25 or 104000k **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

All good

Interior Comment	<u>s</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

Vehicle drove well.

		•						
	Sat. Nav. (basic test only)		~					
Kms:	Reversing camera		V					
Date: 27 Nov 2024								
Name:	Signature:							

Road Conditions During Test Drive: Wet	Central locking	'		
	Remote locking	~		
Engine Timing Mechanism: Cambelt	Sat. Nav. (basic test only)		~	
Evidence of Cam Belt Replacement: No	Kms:	Reversing camera		~
Inspected by: Jayden Roxburgh	Date: 27 Nov 2024			
have read and understood this condition guide.	Name:	Signature:		