

Report ID: 23,021,579 Version: 1 11 Nov 2024 Created:

Make:	Mitsubishi	Model:	Triton	Body Style:	Utility		Pass	Fail	N/A	
Year:	2021	Registration:	NMD455	Reg Expiry:	11 May 2025	Engine				
WoF Expiry:	30 Apr 2025	Odometer:	108,818 Kms	Good No:	23021579	Oil level	~			
VIN:	MMAJLKK10MH01235	Next Service:	28/09/24 or 109000k	Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
diagnostic tes	sting undertaken. The	vehicle has beer	n driven up to 50km/h	from cold. The	Vendor recommends				1	
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	inarge.	Coolant condition	~			
	SC		S S P		D SC	Performance	~			
Key:	Bell	-0			030	Radiator / Hoses (visual)	~			
S = scratch D = dent						Transmission	Transmission			
D = dent R = rust	w dla			215	HIV	Operation	~			
PT = paint defe		r I		$\left[\left(\right) \right]$	<u>17141</u>	Noise	~			
C = crack						Clutch			~	
P = pin dent	HID				7414	CV joints	~			
* = decals	sc 916			The second	FID SOW	Wheel bearings	~			
SC = stone chips						Brakes				
W = significant			S SP		S	Performance	~			
Rodular		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		<u> </u>	
body inspection comments						Tyres (lowest observed tread	d depth	of tyre	1 2s)	
Stone chips in windscreen.						Left front				
						Right front	-	0	mm	
						Left rear		0	mm	
Conditions During Body Inspection: Dry						Right rear	10 mm			
Conditions During Body Inspection: Dry						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~		+	
						Shock absorbers	~		<u> </u>	
						Air Conditioning / Heater	1		1	
						Operation	~			
Interior Comments						Electrical / Accessories	· · · · · · · · · · · · · · · · · · ·			
Seats	Good besi	des drivers seat r	ipped on RH side.			Head lights	~			
	Cood					Tail lights	~			
Carpets	Good					Indicators	~		+	
Panels	Good					Dashboard warning lights	~		<u> </u>	
						Wipers (front & rear)	~		<u> </u>	
Dashboa	rd Good					Window winder FL	~		<u> </u>	
						Window winder FR	~			
General Comments						Window winder RL	~			
Vehicle drove well.						Window winder RR	~		<u> </u>	
Service due	<u>.</u>					Rear view mirrors	~		<u> </u>	
						Radio (basic test only)	~		<u> </u>	
						CD (basic test only)	~		<u> </u>	
						Number of keys	1		L	
Road Conditions During Test Drive: Dry						Central locking	· ·			
Koad Con	attions During Test	Urive:	Dry			Remote locking	~		<u> </u>	
Engine Tir	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~	
-	of Cam Belt Replac	-	lot Applicable	Kms:		Reversing camera				
							~		<u> </u>	
Inspected	d by: Aaron Johnson					Date: 11 Nov 20)24			

I have read and understood this condition guide.

Name:

Signature: