

Report ID: 23,022,275 Version: 2 09 Oct 2024 Created:

Make:	Suzuki	Model:	Splash	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2014	Registration:	HJJ129	Reg Expiry:	27 Jul 2025	Engine	•		•	
WoF Expiry:	13 Jun 2025	Odometer:	148,285 Kms	Good No:	23022275	Oil level	~			
VIN:	TSMEXB32S00750624	Next Service:	152055km	Service Histor	y: Yes	Smoke & fumes	~			
						Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	~			
						Performance	~			
Key:	PT SC	-0	SP P	-161-	SP	Radiator / Hoses (visual)	~			
S = scratch						Transmission	Transmission			
D = dent D = sust						Operation	~			
R = rust PT = paint defe				\int	JHH	Noise	~			
C = crack					SC	Clutch	~			
P = pin dent	HC				ᅰЦ	CV joints	~			
* = decals	ssc 916		<u> </u>	- AL	EIPErs	Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs SD W PW S						Performance	~			
		Note: con				Hand Brake	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram										
Cracking , scuffing and damage to lower front bumper						Tyres (lowest observed tread depth of tyres)				
						Left front	_	5	mm	
						Right front		5	mm	
						Left rear	_	5	mm	
Conditions During Body Inspection: Dry						Right rear 5 mm			mm	
Under Carriage & Under Pennet Inspection Comments						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension		1	1	
All ok						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
Comoto	Good					Tail lights	~			
Carpets						Indicators	~			
Panels	Good					Dashboard warning lights	~			
	, Good					Wipers (front & rear)	~			
Dashboa	rd					Window winder FL	~			
						Window winder FR	~			
General Comments						Window winder RL	~			
Vehicle dro	ve well					Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2	I		
Road Conditions During Test Drive: Dry						Central locking	· · · · · · · · · · · · · · · · · · ·			
						Remote locking	~			
Engine Tir	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)	+		~	
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~	
	•									
Inspected by: Jayden Roxburgh Date: 09 Oct 2024										

I have read and understood this condition guide.

Name:

Signature: